

Awareness on safety culture, security, radiation protection and Environment

Basic Training





Basic training

Agenda

Day 1 – 2 – 3 : ISNES

8h	10h 10h15'	12h15' 12h45'	14h30' 14h45' 1	.6h30'

Day 4 : NPT

8h	9h45'	10h	12h 1	2h30'	15h	15h15'	16h30)'
Training work Preparatio		Training workpla Temporary demobil		Training workplace Demobilizationi, & Debriefing		Test	End	

Meeting : 7h30 Access building (Ground floor) Rem : no camera (GSM) to enter the technical perimeter (Strictly applied)

Culture de Sûreté v03-20140101



2



Basic training

Expectations & rules

- Respect of
- the training
- the trainer
- colleagues
- the infrastructures
- the timing



- Learning – interactivity – share of knowledge



3



Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- **8 Industrial accidents**
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Introduction



5



Rules in case of incidents and/or accidents at the Tihange plant

Fire

Emission of smoke

Effusion of dangerous products

Personal accident







Culture de Sûreté v03-20140101



6



MISE A L'ABRI

Welcome

In case of PIU signal at the Tihange plant





Move to the assembly area





Move to the outside assembly point

Once there: present badge








PIU = IEP: Internal emergency Plan



In case of PIU signal at the Tihange plant





PIU = IEP: Internal emergency Plan





Welcome





9



Safety attitudes

Safety = ?

It is all the measures taken at all stages of design, construction, operation and decommissioning to ensure the protection of the workers, the population and the environment against the effects of ionizing radiation





Positioning



Nuclear safety

What does "Safety Culture" mean ?

It is all that is implemented to :

- **1. Ensure your safety during operations**
- 2. Correctly sort the waste
- 3. Discharge radioactivity into nature
- 4. Ensure the functionality of the plant, in other words, avoiding any deviation from what is planned





Culture de Sûreté v03-20140101

CONTROLATOM

/INCOT1





Nuclear safety

You are a worker and you have to be professional. This means that you must be :

Positioning


- 1. rigorous
- 2. rigorous & vigilant
- 3. rigorous, questioning, communicative and courageous
- 4. questioning, communicative, rigorous and prudent





4 tools to improve Human Performance (HP)

When working at a nuclear power plant, one must be :







4 tools for reducing human errors

Questioning attitude



Attitude interrogative

Attitude interrogative

- Il vaut mieux se poser une question de trop qu'une question trop peu.
- Bien analyser toute action avant de l'exécuter.
- En cas de doute, ne pas hésiter à demander de l'aide.
- Ne jamais hésiter à interrompre une tâche en cas d'incompréhension ou de doute.

Attitude intérrogative





Rigor!



4 tools for reducing human errors

Secured communications



Communication sécurisée

- 1. → Emission du message.
- OK Confirmation par l'émetteur.

Remarque :

- S'identifier clairement soi-même et son interlocuteur.
- Préciser le local, l'action demandée et l'identification complète de l'équipement.
- Donner une seule instruction -

information à la fois.





Rigor!



4 tools for reducing human errors

Adherence to procedures



Adhérence aux procédures

- Respecter systématiquement toutes les procédures et règles en vigueur.
- En cas de doute ou de problème, faire appel à son supérieur hiérarchique.
- 3. Pour les procédures « pas à pas » :
 - lire et comprendre l'action,
 - exécuter l'action telle que décrite,
 - marquer l'action comme terminée
 - (paraphe, trigramme...).

Adhérence aux procédures





Rigor



4 tools for reducing human errors

Pre- and Post-job briefing



Pré et Post-job briefing


5 étapes :

- Présenter l'opération à réaliser, les résultats attendus, le rôle
 - de chacun, les points critiques.
- 2. S'assurer des compétences des intervenants et discuter du retour d'expérience.
- 3. Evaluer les risques et déterminer les parades à mettre en oeuvre.
- Prévoir les outils de prévention d'erreurs à utiliser.
- Examiner le pire des scénarii, les solutions de repli, demander s'il reste des questions.

Après l'intervention, rapporter les infos sur celle-ci (Post-Job) et s'interroger : le pré-job a t'il été suffisant pour éviter des problèmes ?



Rigor



Electrabel @

Adhérence aux



Table of content

1 Introduction

- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

The nuclear power plant









The nuclear power plant

The white plume released from the "big towers" of the plant is :

Positioning

- 1. radioactive
- 2. corrosive
- 3. Water vapor
- 4. radioactive steam






Objectives

Understanding the major operating principles

Location of locals, equipments, ...

Nuclear safety








PWR nuclear power plant (Pressurised Water Reactor)

Composition of the CRP (primary circuit)




- **1. Reactor**
- 2. Primary pumps
- 3. Steam generators
- 4. Pressuriser

Principal role: allowing for the production and the transfer of heat from the reactor core to the secondary system





Fuel - Fission






Fuel - Fission

MWW

wwww






Culture de Sûreté v03-20140101

Electrabel


GDF Svez

Electrabel





5



Reactor vessel


- 1 Rod cluster control assembly mechanism
- 2 Studs
- 3 Cap
- 4 Sealing joints
- 5 Top plate of the core
- 6 Fuel assembly
- 7 Core enclosure
- 8 Guide tubes of the rod cluster control assembly
- 9 Support plate of the guide tubes
- 10 Rod cluster control assembly
- 11 Vessel
- 12 Core support plate
- 13 Instrumentation guide tube
- 14 Damper

Role: contains the core, the internal structures and the control rod drive mechanisms





Primary (system) pump




Role:

- Circulates the water in the primary system
- Ensures the transfer of calories between the fuel and the steam generators


Height: 8 meters Weight 100 tonnes Nominal flow: 20.000 m³/h







Steam Generator (GV)




- 1 Steam outlet
- 2 Secondary humidity separator
- 3 External enclosure
- 4 Cyclone separator
- 5 Primary humidity separator
- 6 External enclosure
- 7 Tube bundle (3680 tubes)
- 8 Brace plates
- 9 Feedwater inlet
- 10 Tube plate
- 11 Partition plate
- 12 Primary coolant outlet
- 13 Primary coolant inlet

Role: allowing the transfer of thermal energy from the water of the primary circuit to the water of the secondary system via vaporisation


- Heat exchange surface: 4,800 m²
- Flow rated of steam: 1,850 t/h







Pressuriser (PPR)




Role: maintaining the pressure of the water in the primary circuit at its normal value of 155 bar

PPR: Primary coolant pressure regulation





General diagram




- 1 Spent fuel pool
- 4 Secondary enclosure
- 5 Containment annulus
- 6 Primary enclosure
- 8 Fuel transfer device
- 9 Reactor vessel
- 10 Steam generator

- 11 Primary coolant pump
- 12 Pressuriser
- 13 Primary piping
- 19 Turbine
- 20 Condensers
- 21 AC generators





Turbine and condenser





34





The nuclear power plant

Operation of the nuclear power plant is ensured independent circuits. How many are there ?

Positioning

- **1.** 3
- 2. 2
- 3. Knowing the number of circuits is not important because, during our intervention, the plant has been shut down





Unit outage (or overhaul)

- Fuel changeout (1/3)
- Statutory preventive and corrective maintenance

The major technical stages of a shut-down :

- Cool and depressurise the water of the primary circuit
- Lower the water level in the circuit
- Open the vessel
- Dump the spent fuel
- Carry out the overhaul
- Reload the fuel
- Close the vessel
- Fill the primary system
- Heat and pressurise the water of the primary system
- Produce the steam and the electricity




Culture de Sûreté v03-20140101

At all times Safety must be maintained





Main phases of the shut down and the water levels







You have to operate in a room that you are not familiar with. In order to get there, you :

- 1. Ask the first person you see, hoping that he does not delay you
- 2. Ask your colleague who went there last

Positioning

- **3. Contact the information desk of the plant**
- 4. Consult the documents that you have been given and apply the identification rules applied at the plant.





Nuclear power plant: Identification

Identification of the circuits

- CRP = primary cooling system
- RPP = primary pressure control system
- CCV = chemical and volume control system
- CPU = purification circuit
- CAB = reactor boron and water make-up system
- RRA = residual heat removal
- CIS = safety injection system
- CRI = interstage cooling system
- CTP = pool processing system
- CAE = containment spray system
- CEX = exhaust exigence system
- CPE = blow-off and vents circuit
- CGN = nitrogen system

- DPV = enclosure isolation valve pressurisation system
- CRC = container filling, draining, flushing and filtering system
- VBR = ventilation of the reactor building
- VSM = turbine hall ventilation system
- VEN = ventilation of the main electrical rooms
- CVT = turbine steam system
- CEE = extracted condensate system
- EAN = main feedwater
- AGH = hydrogen gas supply
- REA = feedwater discharge
- CEB = service water system
- CEI = fire water system
- CEP = potable water system





Nuclear power plant: Identification of the rooms

Identification of the equipment

Equipment located at Tihange 2 :

Every number is important ; ex.: PCT 2 - CEI V123

- PCT 2 : Unit 2
- CEI : Circuit Eau Incendie = Circuit Water Fire
- V123 :
 - V for valve
 - 123 = identification number of the valve





Identification of the equipment

Equipment located in the turbine hall of Tihange 1:

All the digits are important, e.g.: PCT 1 - EAN 1V219VhA

- PCT 1: Unit 1
- EAN: main feedwater system
- 1V219VhA:
 - the first digit (1) indicates the north turbo set (2 for south)
 - V for a valve, Vh is the bigram of the system (however, it is not important to know them when you know that you are on the EAN)
 - A indicates the train (the other train is B)







An identification = ?

Which one is correct ?

A. PCT 2 - EAN 1V219VhA B. PCT 0 - EAN 1V219Vh3 C. PCT 1 - CEB V219 D. PCT 4 - CEB 1V219VhA

Positioning











Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Nuclear security





Nuclear security

Physical protection

What does the nuclear security mean ?

'Nuclear security' (physical protection) encompasses the protections against terrorism, sabotage, theft or other malicious acts involving nuclear material.





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Nuclear safety







Nuclear safety

In a Belgian nuclear power plant, when working, one must be a qualified operator and :

- 1. That is enough
- 2. Be familiar and trained in safety culture as well as having passing the tests at the plant's access
- 3. Be familiar and trained in equipment safety
- 4. Must have passed the tests given at the entrance to the plant







Nuclear safety

I notice a slight deviation :

- **1.** It's not serious, This happens regularly in all types of work
- 2. I immediately inform my Work Supervisor
- 3. I stop everything and contact the emergency number (4444)
- 4. Not serious, but I note it on my DDC





- Ensure the normal operation of the installations
- Prevent incidents and accidents
- Limit their consequences for the environment and the population










Basic principles

Nuclear safety is based on :

The implementation of successive lines of defence

The setting up of 3 leak-tight barriers





The control of the 3 safety functions






Basic principles

Successive lines of defence

Systematically :

- 1. prevent any anomaly through appropriate methods
- 2. monitor to detect any anomaly
- 3. foresee means of action in case of anomaly










Basic principles

3 leak-tight barriers









Basic principles

Mastering of the 3 safety functions

This is the control:

- of the reactivity (neutron)
- of the cooling of the fuel
- of the containment of the radioactive products




In order to guarantee the integrity of the 3 leak-tight barriers under all operating conditions





Simplified diagram of the safeguard systems REP 900 MW (T1)





Control of the 3 safety functions: Equipment and systems

Operation	Control the reactivity	Ensure the cooling of the fuel	Contain the radioactive products
Normal	 Control rod B₄C and neutron- absorbing boron in the coolant/moderator: the water Reactivity: keep the number of neutrons constant from one generation to another 	Steam Generators (GV)	Integrity of the 3 barriers: fuel cladding, primary system, containment. Into depression of rooms BR, BAN N, BAN D
Accident condition	Reactor shut-down - rod drop - injection of borated water by CIS systems	GV powered by EAS or EAA - then RRA IS system then recirculation water cooled by CAE (Ti 1)	 Automatic containment isolation Hydrogen recombination Check pressure, T°, enclosure iodine by CAE

EAS: Emergency supply water EAA: Auxiliary supply water CIS: Safety injection System





Important concepts

Any operation can have an effect on safety

The equipment ensuring one of the 3 Safety functions is "Important for the surety" (IPS).

- to prevent the failure of the barriers
- to limit the consequences of their failure

Example Ti1:

- Primary system (CRP)
- Cooling systems of the reactor (RRA, CRI)
- the safeguard systems (EAS,CAE and CIS)

The failure of one IPS component must not cause the failure of the system




58



Common mode failure

→ Simultaneously causes the unavailability of 2 redundant systems or pieces of equipment





Important concepts

Redundancy Diversification Physical separation





Nuclear safety depends

- On the reliability of the equipment
- On the workmanship of the workers, their skills and their rigour!
- On the efficiency of the organisation of the work



SVez

Adhérence aux







Electrabel @

Electra



Nous attachons la plus grande importance à la protection de tous les collaborateurs impliqués dans l'exploitation de nos centrales nucléaires, du public et de l'environnement. C'est pour cette raison que nous soutenons activement une politique forte de sûreté nucléaire, intervenant à tous les stades du processus d'exploitation de nos centrales. Ensemble avec nos partenaires et contractants, nous mettons en pratique cette politique de sûreté qui se fonde sur les principes suivants:

Súreté = la première priorité

- Nous faisons primer la súreté sur la production en toutes circonstances.
- Nous rendons la súreté omniprésente dans tous les processus opérationnels.
- Nous anticipons, mettons en pratique et suivons strictement les lois et règlements en matière de sûreté nucléeire.
- Nous développons et encourageons une culture de sûreté de haut niveau.

Süreté = processos d'amélioration continue

- Nous définissons des objectifs et les plans d'actions associés pour améliorer le sûreté nucléaire de manière continue.
- Nous évaluons de manière permanente le niveau de sûreté de nos activités et nous les comparons avec les meilleures pratiques et standards internationaux.
- Nous impliquons tous nos collaborateurs dans cette démarche d'amélioration continue et nous veillons à ce qu'ils y collaborent activement.

Des contrôles stricts

- Nous maintenons un dialogue constructif avec les autorités et organismes de sûreté, de même qu'avec les autres parties concernées.
- Nous mesurons en permanence l'efficacité de mise en ceuvre de notre politique de sûreté.
- Nous nous soumettons régulièrement à des audits externes et à des comparaisons internationales.

Philippe VAN TROEYE Directeur Production Belgique - Luxembourg



Culture de Sûreté v03-20140101

Wim DE CLERCQ Directeur Centrale Nucléaire de Tihange



To remember

Nuclear safety is based on :

- The implementation of successive lines of defence
- The setting up of 3 leak-tight barriers
- The control of the 3 safety functions





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Intervention process





Maintenance contributes to the safety process

To guarantee Safety at all times: it is vital to:

Ensure the 3 Safety functions permanently in compliance with the "Technical Operating Specifications" (STE = spécification technique d'exploitation)

These STE :

- Define the normal operating areas
- List the required systems and equipment
- Define the procedure to be followed in case of unavailability





Intervention with the DDC

Blue zone	Orange zone	Red zone
Fire detection and protection, 6kV power, overhead work, etc.	Lockouts	Lockouts, diagnostics,maintena nce, tests
Identify the dangers Define the risks Manages the risks	Identify the dangers Define the risks Manages the risks	Identify the dangers Define the risks Manages the risks

DDC : Disconnection Request






Intervention without the DDC

Blue zone	Orange zone	Red zone
Facility Management, ITS (IT)	Facility Management	Fixed stations (laundry, mechanical workshop,) Instructions in the room
Identify the dangers Define the risks Manages the risks	Identify the dangers Define the risks Manages the risks	Identify the dangers Define the risks Manages the risks








/INCOTTI

CONTROLATOM





71

CONTROLATOM


/INCOTT

Plan


Weekly Planning Meeting (RHP)

Guarantee the SSE

Specific attention during co-activities







Authorise : before completion

- Approval of the work permit (EBL)
- Lockout if necessary (EBL)
- Pre-job briefing (Work Supervisor)
- Granting of the work permit (EBL)

ALWAYS


Pré et Post-job briefing

5 étapes :

- Présenter l'opération à réaliser, les résultats attendus, le rôle de chacun, les points critiques.
- 2. S'assurer des compétences des intervenants et discuter du retour d'expérience.
- Evaluer les risques et déterminer les parades à mettre en oeuvre.
- 4. Prévoir les outils de prévention d'erreurs à utiliser.
- Examiner le pire des scénarii, les solutions de repli, demander s'il reste des questions.

Après l'intervention, rapporter les infos sur celle-ci (Post-Job) et s'interroger : le pré-job a t'il été suffisant pour éviter des problèmes ?








73

CONTROLATOM

/INCOTTE






• The work place card

=> For electrical equipments (> 400V AC and 100V DC)

	Electrabel
CARTE POSTE D	E TRAVAIL
	Tihange 1
FANION	
tese 668256 TEST pour Philippe Vero PCTI-DIV	N* ligne : 0450
DIVERS	
Date - OK 08.2013 15:00 - 0r. autors - 9003	nur / J.Dashelet
Seul OPP/X peux retirer le bordenseu. Prière de rapporter les berderesex penies à la Salle de	Commande.
S* borderess 955821	
	ритьан Уля Цаставадня Частавадня Частавадня Палана
















Authorise : before completion

- Coordination if 2 or more operators
- Several procedures to be complied with
- Specific risks
- Operation with elevated risk



- Understanding of the work to be carried out
- Anticipate any problems
- HP tools

Procedure PREV/INSTR/301







Carry out

Necessary documents:

- DDC
- Local site opening
- Various permits (fire, excavation...)
- ALARA monitoring if necessary

1 - T 2 -	T3 (*)		EN A.T.	OUL/N	ON (*)		LOCAL			_		DATE :	1	/	PAGE :
A co	mpléter a	au fur e	tà mes	ure des	accès	sorties -	Touiou	rs bien	suivre l	a dosim	étrie TC		N	Veau : ALARA	1 - ALARA 2 - ALARA
	EPORTÉE														
								EN	RÉE	SO	RTIE	DELTA	8		
FILM	NOM PRÉN	OM					FIRME	HEURE	DOSE	HEURE	DOSE	(µ\$v)	8	TYPE DE TRAVAIL	EFFECTUE
													8		
								1					8		
													. 6		
													8		
													8		
													÷.		
									<u> </u>				÷.		
													÷		
													÷.		
													*		
											——				
													8		
													8		
													8		
													8		
% DE L	A DOSE ES	TIMÉE =		HμSν		NOUV. SEUIL	AGEN	TSRP	CHEF DE	T RA V A UX	SOMME		€ 8		
POINT	T D'ARRÉT	POUR	CHARGE	DE TRA	VAUX		TRIG.	VISA	TRIG.	VSA	TOTAL H	lµSv			
APPE	LAGENT	SRP									(à reporte	ar)			

Electra	abel	011/4	от	IDE	DE CH		ED				
6073	suez	001		JILL	DE CH	_					
N" DDC :					de travau	Date	11				
EEX :		EEX	: Nom	charge	de travau	x					
	OK		OK		ere fonct	lanal					
PJB reçu:	Oral Form	alisé		rac)							
	DDC	OK NOK N	n -		Envin	onnem Risque	ent de chan s résiduels	tier	OK N	DK NA	
Etes-yous su foortionnel 1	r le bon repère				yens de se douche, e		cessibles et dis	ponibles			
	d'installation de la D	DC					sont connues e	t libres ?			
adaptées	onsignation				Les conditions de travail sont acceptables (T*, éclairage) ?						
Le circuit est d	lépressurisé et vide (lies an et d'évent sont ouverb				chantiers plémentai		apportent pas	de rísques			
	0,) / l'équipement est froid ?			Les	échafauda	iges son	t réceptionnés	?			
Cellule électri consignée ?	que 6 kV; 380 V;				produits d kage est p		x sont étiquete	is ?			
Absence de te	mailon quadilitaire						res de levage s	ont en	п		
	d'exécution de la DD is d'exécution sont	с			re de cont		d tröhuchamaa	Loot			
adaptées ?					Les risques de chute et trébuchement sont protégés ?						
Les moyens sont mis en l	de prévention définis place ?			Les	Les pièces chaudes sont protégées ?						
Les moyens place ou disp	FME nécessaires sont e ponibles ?						ants sont proté				
	cas de PIU (mise à l'i les intervenants pour s					er en sé	curité puis év	acuer			
Date	Nom	Prénom		sa	Date		iom	Prénom		Visa	
			+		-						
Travaux à rè	sques élevés suivant p	rocédure PREV/IN	ISTR/3	101 (Cor	nsigne 010	1 coché	e dans la DDC)		OUI	/ NON	
Pour les trav	vaux à risques élevés			ec age	vt SRP)				LOK N	W NA	
Le chantier e	on botton		<u>-</u>				nes est placé à	l'entrée du			
	préalables sont		-	cha	ntier et va	idé par	CARE SRP				
correctes (T											
	ST vous avez répondu NOK à une des questions, contactez votre chef d'équipe ou le responsable EBL <u>Musures complémentairez pripes</u> :										
Vicito quatia	dienne du Chargé de tr	mour Electrobel	nour l	or tenu	ward daar	or floor	6				
Date Trig		avaux clettrabel	Visa	as diav	Date	Trig	Commentair	85	-	Visa	
			-			-					
	1										

Ins. Code (Rdf.):	ZNO 10010101636/000/01 -	Date	03/09/2010 - MWC Publisher	PCT OMDP -	Doc. miles :	GDD/GP1004	ZNT10000762633/000/02	

Electrabel		PERM	US DE TRA / Tihange 2	VAIL / 2EM		DDC 1550469
POSTE TECHNIC ZONE DE TRI: LOCALISATION: Description: Phase Révision:	CLAPET AN 2 513327 réfection de la	TI-RET.S/				TD ann.1: X
DEBUT DU TRAV		1	FIN DU TR. Date: Responsable Ins		A	00:00:00
Changement d	Chargé des tr					
Date:	Date:	avaux	Date:		Date:	
Nom:	Nom:		Nom:		Nom:	
Signature:	Signature:		Signature:		Signature:	
PARTENAIRES DDC Int.Resp.de travail		cois Lantin		Date		Signature
PERMIS	Permis par	Date	1	D ann.1 L	DC	
SUPERVSION	L REMACLE	01.07.201		5	96907 ;	
AGREE REVIEW	C PINTE R RADOUX	04.07.201				
SAFETY	B ROBA	04.07.201		1000		
SECURE REQUALIF	C PINTE	05.07.201	11			
INSTALLATION						TD ann.1
25-CIRC CI20	Circuit DOIT être v	ide & Hors pre	ession			x
BERCUTION						TD ann.1
01-TVX 0101	Travaux à risques él	evés				
09-3INC 0931	Risques liés à une z	one ATEX				
11FME 1102	Niveau FME standar	d				
14ROC 1401						
14-1RCH 1411	Compléter le check	list replis chant	ier			
15MPI 1501	Moyens de prot.indi	viduels requis				
99MYSELF 100	Voir short text ou la voir agent RP	ong text				x
GRORES				-	11	te d'obj. aren.1
	n de la fuite au raccon PCT2-AGH-C5 CLAPET ANT	67	ONNES H2 CIRC	1.8	LB	se v voj. 2014
primé par: CHRISTI			05.07.2011 07:54			Page: 1/3






POSTE TECHNIQUE:	PCO-12-AC 50-GK AUTOMATISME AC		
ZONE DE TRI: LOCALISATION: Description: Phase Révision:	PCO-12 Dédoublement conta	LOCAL: acts position D1	TD ann.1:
DEBUT DU TRAVAIL	:07.01.2010 08:00:0	0 FIN DU TRAVAIL:07	7.01.2010 08:00:00
Date:		Date:	
Responsable Installations	chargé des travaux	Responsable Installations	Chargé des travaux
Changement du Ch		<u>an an a</u>	
Date:	Date:	Date: Nom:	Date: Nom:
Nom	Signature:	signature:	Signature:
Nom: Signature:	signature.		
	pignature.		
	Nom	Pate	Signature
Signature:		Date	Signature
Signature: PARTENAIRES DDC		Date	Signature

Indicate the names of the CDT and not the three-letter code








Culture de Sûreté v03-20140101

CONTROLATOM

VINCOTTE

ACADEMY






VINCOTTE

CONTROLATOM




Descriptio 25-CIRC	CI20	Circuit DOIT être vide & Hors pression	
		ATTENTION, SERVICE PRODUCTION A consigner CIRCUIT VIDE	
02-PROC	0201	Procédures requises	
07-3CHU	0732	Tout travail sur un équipement AO doit faire l'obiet d'une procédure ou d'un mode opérato Chute de plain pied	
		Chute de plain pied: sols glissants, irréguliers ou encombrés: nettoyer, baliser.	Correct markup
U7-0AMB	0701	Brun	
07-91PP	7101	Danger lié au bruit Consigne: porter les protections individuelles contre le bruit Blessure aux yeux	
		Port des MDL et lupettes de sécurité	
08-4CONT	0841	Risque de contamination surfacique	
		Danger de contamination surfacique du chantier Consigne: voir agent RP pour mesures et consignes	ntamination risks
08-4CONT	0842	Risque de contamination atmosphérique	Italiination 115K5
IU-EINV	1002	Danger de contamination atmosphérique par les gaz radioactifs Consigne: voir agent RP pour mesures et consignes	
		Disposer des moyens de prévention anti-pollution (absorbants, barrières, obturateurs dégouts,	#.)
STE OBJETS	des OR	DRES	
Liste Obj Avis	ets 500	1358984 Ouverture pour nettoyage ou remplacement 11078212	
		Ouverture pour nettoyage ou remplacement	










Réunion d'ouverture de chantier Qui: Responsable des travaux et EEX •Quoi: Présentation de Entervention, risques, controle compréhension des intervenants.... Comment: Réunion sur le chantier + Canevas 'PV Ouverture de chantiers' Quand: Avant l'intervention sur le chantier

Carry out Electrabel GDE S


OUVERTURE DE CHANTIER

N" DDC :				_		_			Date	:				
								e travau e travau						
EEX :		-		<u> </u>		anic	narge Ge	e travati						
PJB recu: 0	Oral OK	Forma		×	NOK	-	Repèr	re fonct	ionnel :	:				
				<u> </u>		1		Enviro		ent de chant	lier			
	DDC		OK	NOK	NA					résiduels	act	OK	NOK	NA
Étes-yous sur l	le bon repère			_		1	Moyer			cessibles et dis	ponibles		_	
fonctionnel ?	-					1		ouche, e				<u> </u>	ᆜ	<u> </u>
Consignes d'i Les consignes			DC DC			4	Les iss	ues de s	ecours s	ont connues et	t libres ?		Ц	
adaptées	d installation	SOME							de travi	ail sont accepta	bles (T*,			
Effets de la co							éclaira	age) ?						_
Le circuit est dép vannes de drain										apportent pas	de risques			
manomètre à 0,		C DUPERCES					supple	émentair	res 7					
La ligne et/ou l'é	équipement est	frold ?					Les éd	hafauda	ges sont	réceptionnés	7			
Cellule electriqu	A FRY SHOW		_	_	_					x sont étiqueté	s ?		П	
consignée ?		-					Stocka	age est p	révu ?					
Absence de tens			. 🗆			4		gins et a de contr		res de levage so	onten			
Consignes d'e			-	_	_	-				t trébuchemen	tsont	_	_	
adaptées ?				Ш	Ш	Les risques de chute et trébuchement sont protégés ?								
Les moyens de sont mis en pla		définis				1	Les più	èces cha	udes so	nt protégées ?				
Les mouens EME péressines sont en														
place ou disponibles ?														
APPEL: en cas de PIU (mise à l'abri ou évacuation) : mettre le chantier en sécurité puis évacuer Signatures des intervenants pour prise de connaissance des consignes														
Signatures des	intervenants	nour pr	rise de ce	mais	sance	des :	consign							
		pour pr			sance				N	om	Prénom			/isa
Signatures des Date	Nom	pour pr	rise de co Prénom		sance	des Visa		Date	N	om	Prénom		,	/isa
		pour pr			sance				N	om	Prénom		`	/isa
		pour pr			sance				N	om	Prénom		`	/isa
		pour pr			sance				N	om	Prénom		,	/isa
Date	Nom		Prénom			Visa		Date			Prénom			
	Nom		Prénom			Visa		Date			Prénom	0		
Date	Nom ues élevés su	ivant pro	Prénom	PREV/	INSTR	Visa 1/301	1 (Consi	Date			Prénom	0		
Date Travaux à risq	Nom ues élevés su	ivant pro	Prénom	PREV/	/INSTR	Visa 1/301	1 (Consig	Date gne 010: SRP)	1 cochée	e dans la DDC)		0 0K		
Date Travaux à risq Pour les trava Le chantier est	Nom ues élevés su ux à risques é t balisé	ivant pro	Prénom océdure hargé de	PREV/	/INSTR	Visa 1/301	1 (Consig c agent 5	Date gne 010: SRP)	1 cochée					ION
Date Travaux à risq Pour les trava	Nom ues élevés su ux à risques é t balisé réalables sont	ivant pro	Prénom océdure hargé de OK	PREV/	/INSTR	Visa 1/301	1 (Consig c agent 5	Date gne 010: SRP)	1 cochée	e dans la DDC) nes est placé à l		OK		ION
Date Travaux à risq Pour les trava Le chantier est Les mesures p	Nom ues élevés su ux à risques é t balisé réalables sont 0 ₂)	ivant pro	Prénom océdure hargé de OK			Visa V/301	1 (Consig c agent 5 Le pan chanti	Date gne 010: SRP) nneau de ier et val	1 cochée e consign	e dans la DDC) les est placé à l CARE SRP	"entrée du	OK		ION
Date Travaux à risq Pour les trava Le chantier est Les mesures p correctes (T*, 0	Nom ues élevés su <u>ux à risques é</u> t balisé réalables sont D ₂)	ivant pro lievés (c t	Prénom océdure hargé de OK			Visa V/301	1 (Consig c agent 5 Le pan chanti	Date gne 010: SRP) nneau de ier et val	1 cochée e consign	e dans la DDC) les est placé à l CARE SRP	"entrée du	OK		ION
Date Travaux à risq Pour les trava Le chantier est Les mesures p correctes (T*, c Si vous over n	Nom ues élevés su <u>ux à risques é</u> t balisé réalables sont D ₂)	ivant pro lievés (c t	Prénom océdure hargé de OK			Visa V/301	1 (Consig c agent 5 Le pan chanti	Date gne 010: SRP) nneau de ier et val	1 cochée e consign	e dans la DDC) les est placé à l CARE SRP	"entrée du	OK		ION
Date Travaux à risq Pour les trava Le chantier est Les mesures p correctes (T*, c Si vous over n	Nom ues élevés su <u>ux à risques é</u> t balisé réalables sont D ₂ }	ivant pro ilevés (c t d une de prises :	Prénom océdure hargé de OK	PREV/ e trava NOK	AINSTE NA	Visa t/301 avec	1 (Consig c agent 5 Le pan chanti	Date gne 010: <u>SRP)</u> nneau de ier et val	1 cochée e consign idé par t se ou le	e dans la DDC) res est placé à l CARE SRP responsable EE	"entrée du	OK		ION
Date Travaux à risq Pour les trava Le chantier est Les mesures pu correctes (T*, 0 Si vous avez n Mesures come	Nom ues élevés su <u>ux à risques é</u> t balisé réalables sont D ₂ }	ivant pro ilevés (c t d une de prises : gé de tra	Prénom océdure hargé de OK	PREV/ e trava NOK	AINSTE NA	Visa //301 avec ez vo	1 (Consig c agent 5 Le pan chanti otre chej	Date gne 010: <u>SRP)</u> nneau de ier et val	1 cochée e consign idé par t se ou le	e dans la DDC) res est placé à l CARE SRP responsable EE	rentrée du	OK		NA
Date Travaux à risq Pour les travai Le chantier est Les mesures pro correctes (Tr.) Si vous over n Mesures come Visite quotidie	Nom ues élevés su ux à risques é t balisé réalables sont 0 ₂₀) épondu NOK épondu NOK	ivant pro ilevés (c t d une de prises : gé de tra	Prénom océdure hargé de OK	PREV/ e trava NOK	AINSTR NA	Visa //301 avec	1 (Consig c agent 5 Le pan chanti otre chej	Date gne 010: <u>SRP)</u> meau de ier et val <i>f d'équiy</i> x à risqu	1 cochée e consign idé par t be ou le es élevé	e dans la DOC) res est placé à l CARE SRP responsable El 3	rentrée du	OK		NA
Date Travaux à risq Pour les travai Le chantier est Les mesures pro correctes (Tr.) Si vous over n Mesures come Visite quotidie	Nom ues élevés su ux à risques é t balisé réalables sont 0 ₂₀) épondu NOK épondu NOK	ivant pro ilevés (c t d une de prises : gé de tra	Prénom océdure hargé de OK	PREV/ e trava NOK	AINSTR NA	Visa //301 avec	1 (Consig c agent 5 Le pan chanti otre chej	Date gne 010: <u>SRP)</u> meau de ier et val <i>f d'équiy</i> x à risqu	1 cochée e consign idé par t be ou le es élevé	e dans la DOC) res est placé à l CARE SRP responsable El 3	rentrée du	OK		NA
Date Travaux à risq Pour les travai Le chantier est Les mesures pro correctes (Tr.) Si vous aver n Mesures come Visite quotidie	Nom ues élevés su ux à risques é t balisé réalables sont 0 ₂₀) épondu NOK épondu NOK	ivant pro ilevés (c t d une de prises : gé de tra	Prénom océdure hargé de OK	PREV/ e trava NOK	AINSTR NA	Visa //301 avec	1 (Consig c agent 5 Le pan chanti otre chej	Date gne 010: <u>SRP)</u> meau de ier et val <i>f d'équiy</i> x à risqu	1 cochée e consign idé par t be ou le es élevé	e dans la DOC) res est placé à l CARE SRP responsable El 3	rentrée du	OK		NA



85






Travaux à risques	élevés	suivan	t procédure PREV/INSTR/301	(Consigne 0	101 cochée	e dans l	a DDC)	OUI/	NON
Electrabel ANNEXE 15 : OUVERTURE LE CHANTIER									
Date : N*DDC : EBL : Nom chargé de trave	F	our les 1	ravaux à risques élevés (chargé de l	travail EBL aveo	agent SRP)				
EEX : EEX Nom charge de trave OK OK P3B repu: Ori Page repu: Ori				NOK NA				ОК	NOK NA
DDC or. Nor. Na Env onnement de chantier or. Nor. Na fbravous surit bon repère forctonen? Image: Compressible et depontées (Hé dout a extensive et depontées) Image: Compressible et depontées Image: Compressible et depontées Compress d'Installation de la DOC Les subset et depontées Image: Compressible et depontées Image: Compressible et depontées	L	e chanti.	er est balisé		Le panneau chantier et		gnes est placé à l'entrée du r CARE SRP		
Les consignes d'installations sont			res préalables sont (T°, O ₂ ,)						
College Sectores of PF, 200 (vez répondu NOK à une des questio complémentaires prises :	ns, contactez vo	otre chef d'éq	uipe ou l	e responsable EBL		
Sections de la literative pour alla de constitution des sons de la literative de la literat									
Pour les tennes à résours l'étres									
Date Topic Connectative and a first sector for the secto									
	Visite	quotidie	enne du Chargé de travaux Electra	bel pour les tra	vaux à risqu	ies élevé	<u>s</u>		
	Date	Trig	Commentaires	Visa	Date	Trig	Commentaires		Visa







Respect the instructions of the site board !

		N° de DDC :			Chantier :						
Flor	ctrabel	EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :		
		BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :		
GT	DF SVez	DATE :Du	au	LOUAL .	AGENT SRP	Nom :	Trig :		SRP :		
			au	Travail à riegue élev	A SAMA SA STATUTA A SAMA SA	NOTT .					
	Mesu	res d'irradiation			e. O/N Sroui, mour.						
6		Au poste de travail		Risques identifiés :							
Date		(µSv/h)						- A			
		w 7									
				Consignes pour inte							
				••••••	••••••	••••••	•••••	•••••	• • • • • • • • • • • •	•••••	
				••••••	••••••	••••••	•••••	•••••	•••••••	•••••	
				1							
Mesure	es de contaminati	on et de sécurité a	vant ouverture								
-	contamination	contamination atmosphérique	sécurité		••••••	••••••	•••••	•••••	•••••••	•••••	
Date	surfacique (Bg/cm ²)	atmospherique (Bq/m ³)	sécurité (% LIE H ₂ ,% O2, T° WBGT)	••••••	••••••	••••••	•••••	•••••	•••••••••	•••••	
						•••••	•••••		• • • • • • • • • • • •	•••••	
				Point d'arrêt :				Lavánan	VICA	Deter	
				Point d'arret.				Levé par:	VISA:	Date:	
									1		
Moouro	oc do contominati	on et de sécurité a	nràs auvortura								
wesure	es de contaminati	on et de securite a									
Date	contamination surfacique	contamination atmosphérique	sécurité (% LIE H ₂ ,% O2, T° WBGT)								
Date	(Bq/cm ²)	(Bq/m ³)	T° WBGT)								
				Consignes pour acc	àc :					98	
				consignes pour acc							
				•••••••••••••••••••••••••••••••••••••••							

LATOM






Respect the instructions of the site board !

	-	2	N° de DDC :			Chantier :	/				
	Elec	trabel	EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :	
		of svez	BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :	
		J. BUCE	DATE : Du	au)	AGENT SRP	Nom :	Trig :		SRP :	
					Travail à risque élev	é:O/N si oui, motif :					
	Mes	sures de sécurité (% LIE H ₂ ,% O2, I*	WBGT)	Risques identifiés :						
		Avan	t ouverture								
	Date	Mesure de :	Mesure de :	Mesure de :							
	-			-	Consignes pour inte	rvention :					
	-										
		Aprè	s ouverture					· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · ·	· · · · · · · · · · · · · ·
	Date	Mesure de :	Mesure de :	Mesure de :				•••••	•••••	•••••	
	-		P			••••••			•••••	•••••	
	5				Point d'arrêt :				Levé par:	VISA:	Date:
	-				rome d'arree.				Leve par.	VISA.	Date.
	-										
	Consigne	es pour accès :									
) - 🜍 - (3				
		•••••		• • • • • • • • • • • • • • • • • • • •							
Culture de			• • • • • • • • • • • • • • • • • • •	• • • • • • • • • • • • • • • • • • •	•••••				• • • • • • • • • • • • •		

B. [HORS-ZONE] Panneaux en polystyrène, format 420 x 594 avec impression direct






Carry out: intervention / qualification

- During the operation :
 - Respect the instructions and the wearing of MPI
 - Securing and marking of the site
 - Management of waste and cleanliness of the site
 - Quality control
 - Identification and communication of deviations
- In case of emergency :
 - Putting the workplaces into safety, then evacuate
 - Work permit suspended
 - Formally authorised resumption (end of incident)
 - Interrogative behaviour in case of deviations





Electrabel

Electrabel 6

Electrabel





nécessaires sont en



Nom

During the operation

In case of emergency t mis en place

- PIU (mise à l'abri ou évacu ation) : mettre le chantier en sécurité puis évacuer Secure the sites, then evacuate \succ
- Authorisation to suspend work
- Restart formally authorised = end of incident


Nom

Questioning attitude in case of deviations



Prénom





Carry out : Demobilization / Report

- Demobilization (with SRP in controlled area if required by DDC)
 - Reworking of the installation and its environment
 - Removal of logistics (tools, scaffolding,...)
 - Re-establishment (insulation, marking, protection,...)
 - Removal or parking of handling equipment
 - Removal of waste (cleanliness of the site)
 - Housekeeping
 - demobilization check-list (back of the local site opening form")
- Return of the DDC:
 - Work completed and correct
 - Site cleared




Culture de Sûreté v03-20140101

I return the site at least in the condition I found it!







CHAPITRE 15 : CHECK LIST REPLI DE CHANTIER

			Date :	
	Re	pli en O	rdre	<u>Commentaires</u>
	ОК	NOK*	NA	
Le chantier a-t-il été contrôlé par un agent SRP (<u>si demandé par</u> <u>les consignes RP à l'entrée du chantier</u>) ? - Local et équipements ? - Outils ?				Si nok, contacter l'agent SRP.
<u>A-t-on</u> évacué le matériel et l'outillage ?				
Le matériel et l'outillage sont-ils décontaminés et remis en état ?				
Le chantier est-il décontaminé ?				Si nok, prévenir les SG de la fin de chantier
Le chantier est-il nettoyé (Nettoyage <u>final</u> local et équipements) ?				Si nok, prévenir les SG de la fin de chantier
Repérage (étiquettes, labelling,) remis en conformité ?				
Réfection des peintures dégradées durant l'intervention réalisée ou planifiée ? (Local et équipements)				
Signalétique relative au chantier (balisage, affiches, "carte de défaut") retiré ?				







Realize : Work demobilization

Les coffrets électriques <u>sont ils</u> verrouillés ?		
Déchets évacués vers les lieux de stockage prévus à cet effet ?		Si nok, prévenir les SG de la fin de chantier
Echafaudages démontés ?		Si nok, prévenir le coordinateur d'échafaudage
Pénétrations coupe-feu correctement refermées ?		
Engins de manutention en position de garage ?		
Dalles, caillebotis, garde-corps correctement remis en place?		
Calorifuge correctement remis en place ?		

* Dans les cas ou vous répondez NOK : rédiger un avis et inscrire le numéro en commentaire (sauf commentaire existant),

	Si non, prévenir le coordinateur d'échafaudage
	0 0 0 0 0 0 0 0 0 0 0 0

* Dans les cases au vous répandez NON : rédiger un avis et l'inscrire en commentaire (sauf commentaire existant).
** pour équipement de sûreté l'échafaudage doit être démonté avant fin requalification

Clas. Code (Réf.) : ZNO 10010101636/000/00 - Date : 21/09/2009 - MWC Publisher : PCT 0MDP - Doc. mbre : GDI/GPI/004 : ZST10000762633/000/02

	Trigramme	Visa	ĺ
Validation Chef de Travaux : Culture de En zone contrôlée, <u>tout</u> repli de chantier doit être validé par la SRP (<u>si</u> demandé ana les consignes RP à l'entrée du chantier) :	Sûreté v	03-201	401(





Why a **GOOD** demobilization

C'est arrivé à la CNT :



Un morceau de chiffon a été oublié sur une vanne (CVC V850 en salle des machines de Ti2).



Du fait de la température élevée, il a commencé à se consumer. Lors de son passage en local, un agent a pu le retirer avant qu'il ne s'enflamme.








Soyons attentif à ne déposer aucune charge combustible sur les équipements chauds.

Les installations sont rendues dans un état de propreté meilleur qu'avant notre chantier.







Before return to service


- removal of administrative lockout
- **Requalification :**
 - Check
 - Works
 - Tests
 - Validation

Show that the equipment can fulfil its function

Responsibility of the CdT (EBL if work with elevated risks)







Technical-administrative closing

Post-job briefing

- REX
- Compilation of report
- Updating of documents
- Final acceptance

Participants

- EBL Work Supervisor
- Foreman or EEX foreman





To remember

	Conventionnal works	Elevated risks level works		
Pré job Briefing	CdT EBLWorkteam	CdT EBLWorkteam		
Workplace opening	- CdT	CdT EBLSRP officer		
Daily visit	NA	CdT EBL		
Work demobilization	CdT + SRP if necessary (see rules on the DDC)	CdT + SRP if necessary (see rules on the DDC)		

Adhérence aux procédures



Electrabel Electrabel







Electrabel



To remember



Adhérence aux procédures



Culture de Sûreté v03-20140101

98

Electrabel @



Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- **6 Quality assurance**
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Quality assurance







What does "Quality Assurance" mean ?

Positioning

It is:

- 1. Being sure of what you do
- 2. The assurance that you are ensuring quality
- **3. Complying with the rules for the important aspects**
- 4. Implement procedures to ensure that what needs to be done is actually done







What does "auto-inspection" mean (P.A.C) ?

Positioning

It is:

- 1. the inspection of my work automatically done my an EBL agent
- 2. the inspection that my company does after each operation
- 3. the inspection of the content of the vehicles entering the site
- 4. my own inspection of the operations that I have carried out







What does "stopping point" mean (P.A.)?

Positioning

It is a:

- **1. emergency shut-down control device**
- 2. control point of the vehicles authorised to drive on the site
- 3. checking point of the completed work, because it is an important step for safety
- 4. immediate stoppage when noting a deviation





Quality Assurance



Quality assurance is :

All the **pre-established** and **systematic** actions necessary to **inspire the appropriate level of confidence** that a **product** or **service** will comply to requirements related to the quality.






Quality Assurance

The principles for the implementation of QA are :

Plan - "I define what I want to do" DO "I write what I do" "I do what I have written"

Check - "I measure what I do"



ACT - "I react to reports to improve "





- a Monitored Quality work
 - → compliant with procedure !
- Basis of an operation = copy of the "master document"
 → Stamp



DOC. MAITRE Ti. 2 CL^t HISTORIQUE Si ce tampon est rouge → Applicable to Tihange 1

→ Applicable to Tihange 2





➔ Applicable to Tihange 3





Quality Assurance

Types of procedures ?

1. "Step by step" procedures

Completed on site, during the operation

- \rightarrow Step by step, order of sequences to be adhered to
- When an incorrect action would have an immediate impact on nuclear safety or reliability
- During activities where we cannot rely on our memory
- During long, tiring, repetitive or complex jobs
- During unfrequent activities, done occasionnaly and with some degree of complexity



Réf.	642310/EF/500					
Ap	oplicable à	Ti. 1	Ti. 2	TL 3	Site	
Suiv	ri AQ				OUI	
Proc	Procédure à utiliser pas à pas			OUI		
Procédure à utiliser en référence			NON			
Procédure pour information		NON				







Quality Assurance

Types of procedures ?


2. "In reference" procedures

Available on the site

- \rightarrow Can be completed at the end of the operation
- Compared to the « Step by step procedure », the « in reference procedure » is used when there is no immediate consequence in of of incorrect action, when the order of sequences is not important
- During activities made of small tasks that can easily be remembered



Culture de Sûreté v03-20140101





dhérence aux





Types of procedures ?

- 3. "For information purposes" procedure
- Réf.
 642310/EF/500

 Applicable à
 Ti. 1
 Ti. 2
 Ti. 3
 Site

 Suivi AQ
 OUI
 OUI
 OUI

 Procédure à utiliser pas à pas
 OUI
 OUI

 Procédure à utiliser en référence
 NON

 Procédure pour information
 NON

Not necessariloy available on the intervention site

- When the execution of the work is frequent or easy to realize.
- When the whole task can be done by heart











Check points (CQ)

The auto-check point (A.C.)

- Done by the operator
 - →Formalised with his three-letter code

The convocation point (P.C)

The activity <u>can not be pursued</u> without the approval of the inspector.

→ Done by an "inspector"

→ Formalised with the three-letter code of the operator and the inspector

VINCOTTE ACADEMY CONTROLATOM





The stopping point (P.A.) → Compulsory stop !

The activity can not be pursued without technical counterchecking.

- ➔ Done by an "inspector" or in his presence
- ➔ Formalised with the three-letter code and the signature of the inspector as well as the inspection date

Réf. de	la p	rocédure type : PCT3-7493	27/EF/0	001 – PCT1-678300/EF/008 – PCT1-678341	1/EF/007	Gestion : 0SE1
Requis		S.T.E. chap 16		Périodicité : 6 cycles		Durée :
par :	X	Spec Constructeur		A faire on révision.	Oui/non	
	X	RSQ		Fait par (Trig.) : Visa :	Le	
PENDA	NT	LE QUALITE TL'EXECUTION LE QUALITE APRES REA TIONS :	oui/ non LISAT	POINT D'ARRET à lever par un CHEFDE BLOCoui - nonPOINTS DE CONVOCATION contacterION :Par (Trig.) :		Visa :
ORDER	R N ^o	:		WCA N° :		
ture de l NOTIFI	Sûre	eté v03-20140101 TION N°:				111



The "AQ" spare parts









QA Spare parts: replacement equipment







LL	LUTITIDEL	MAUS	
	Accord Con	ntrôle Archivage (Store)	
Art. :	PCT 130104		
Lib. :	CODE: 977 01 694	T 302 NF ADR (SANS PILOTE) SSORT+JOINTS QUALITE VAN	
			VIAC
Classe d	le sûreté: 1EA	AIA : Non	
Fourniss	seur : ASCO-JOUCOMATIC BEN	ELUX PO : 45004385	513/30
Certifica	at: JCRL08 2466306 Ident. /Marc	.: LOT 2466306-01	
Date En	tree : 22/01/09		
vo:Dale 1%1	bilcation :	Date Peremption : 31/03/18	









The measurement and testing instruments (IME)

- Have the range of use, the desired range and precision,
- Are in operating state,
- Are maintained,
- Calibrated in pre-determined increments
 - => calibration sheet, valid calibration label.
- → Recording of the use of an IME to trace related operations.





STORIA: INTERMES N.V. Doc: 0902-04129 ID: PCT-IME-06-GENE-00138

ated : 18 Feb 2009





Nuclear "housekeeping" includes :

- cleanliness of the buildings, equipment and instruments
- state of the paintwork
- prevention and protection against fire (including waste)! closed bins!
- good seismic practices
- protection against radiation (including contaminated waste)
- state and reassembly of insulation
- clearance of access areas and passages
- protection of devices and equipment
- inspection of the correct state and identification of equipment
- use and monitoring of signalling (Safety, Security,...)
- inspection and control of ambient conditions
- other quality maintenance requirements
-





Who checks, inspects or monitors : Summary






Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- **8 Industrial accidents**
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Legislation





Positioning



Legislation

The FANC refers to :

- **1. Feminist Association of Nuclear Centres**
- 2. French Agency of Nuclear Centres
- **3. Federal Agency for Nuclear Control**
- 4. Federal Agency for Nuclear Compliance





Legislation



- European directives
- Code of Well-being at Work
- RGPT
- RGIE,...

Responsibilities

- Employer
- Members of the line management
- Workers

Each one has a Legal, Civil and Moral responsibility







Health and safety legislation at work

The employer


- Manages the risks
- Plans the prevention
- Instructs and trains the workers
- Informs the external companies
- Creates procedures and analyses the work stations
- Takes the necessary measures to avoid any accidents





Health and safety legislation at work

Line management



- Inspects the working and protection equipment, . . .
- Inspects the task sharing (skills)
- Monitors the respect to the instructions
- 5 a. a. a.
- Examines incidents and accidents





Legislation





YOUR responsibilities:

- Correctly use: machines, products,...
- Do not modify the safety devices
- Immediately report any dangerous situation
- Stop work and inform your manager if you notice serious and immediate danger
- Cooperate with security for your safety








Legislation

Parties "traditionally" involved in Belgium









Nuclear players in Belgium






Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- **8 Industrial accidents**
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level


- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Industrial accidents





Work accidents

The work accident : (Chap I, Section 2, art. 7)

Sudden event Damage (corporal or moral) External cause to the victim During and because of the execution of the work permit,








→ human behaviour





Work accidents



What happens if one removes half of all dangerous situations?






At all times: react to deviations!

Each player must:

- Know the requirements to be complied with
- Have a questioning attitude
- Know how to treat deviations
- Communicate
- Start his processing and

his traceability







All the time :

React to the deviations !

COF 1002	Prive Chapterio	Standa	rd		Interne	SMAR
Titre: FE Standard:						
Description succincte de la situation:						
Structure techniqu	e: Stte	Tihl Tih2 1	īh3 🔲 Da	ite de l'obser	vation:	
	e: Site 🗌	Tihl Tih2 7	ïh3 □ Da	ite de l'obser	vation:	
Préoccupation: Cette situation s'es	t-elle déjà p	<i>Tih I Tih 2 T</i>		ite de l'obser	rvation:	
Préoccupation: Cette situation s'es Bonne pratique ? o	t-elle déjà p ui / non			ite de l'obser	rvation:	
Préoccupation: Cette situation s'es Bonne pratique ? o Risque incendie ? o	t-elle déjà p ui / non ui / non	roduite par le passé ?	oui / non	ite de l'obser	vation:	
Préoccupation: Cette situation s'es Bonne pratique ? o Risque incendie ? o	t-elle déjà p ui / non ui / non		oui / non	ite de l'obser	vation:	
Préoccupation: Cette situation s'es Bonne pratique ? o Risque incendie ? o	t-elle déjà p ui / non ui / non	roduite par le passé ?	oui / non	ite de l'obser	vation:	
Préoccupation: Cette situation s'es Bonne pratique ? o Risque incendie ? o	t-elle déjà p ui / non ui / non	roduite par le passé ?	oui / non	ate de l'obser	vation:	

*Pour les entreprises extérieures, merci de remplir ces informations complémentaires:

Rédacteur:	
Nom de l'entreprise:	
Adresse e-mail:	

Date de redaction:	Redacteur*:	Service:

Exemplaire complété à renvoyer au secrétariat CIM (par mail: <u>CNT CIM – Secrétariat</u>)

Ref. : ZNO 10010102113/000/08 - Date : 21/06/2012 - Editeur : HECT CIM - Doc. mère : REX/00/016 (ZST 10001484504/000/00)





Work accidents

Conclusion










Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

The risks





Definition

	Characteristics and/or intrinsic capacities which are the
Dangar	source of damages, specific to an object (agent,
Danger	machine,), a process (movement, transport,) or
	a situation (climate, storage)
Diele	Threat that, with a certain probability of occurring, can
Risk	have damaging consequences

Risk = Probability and Consequence


ZERO risk does not exist






The risks

Principles: reduction of the risk



1 Elimination










Principles: reduction of the risk

2. Reduction

3. Collective protection

DANGER: RUN FOR YOUR LIFE 4. Individual protection MPI



5. Warning, Instruction, Training, Signalling









Risks and dangers

What is the risk at the source of the most work accidents at Tihange ?

- **1. Displacement**
- 2. Radioactivity (irradiation contamination)
- 3. Cuts
- 4. Electrocution





Awareness on safety culture, security, radiation protection and Environment

The risks relating to displacement





The risks: relating to displacement

Know:

how to move
the authorised areas



- Corporal lesions
- Fractures

Risk of falling, stumbling and slipping = First factor accidents at the CNT







The risks: relating to displacement

Slipping

→ Adherence between shoes and the walking surface.

Main causes:

- damp or greasy surfaces
- accidental spills
- bad weather
- poorly secured mats
- floor coverings







The risks: relating to displacement

Stumbling

→ Loss of balance

Main causes:

- obstructed view
- poor lighting
- clutter
- folded mats
- exposed wires
- drawers at floor-level not properly closed
- uneven walking surfaces (steps, sills, etc.)











HOW DOES ONE AVOID FALLS ?

Keep the site clear and respect the rooms

- Immediately clean up any spills,
- Clearly mark high-risk areas,
- Clean the floors,
- Keep the passages free of any obstacle and clutter,
- Properly secure all mats and floor coverings so that they remain flat,
- Always close drawers,
- Remove all waste,
- Cover the wires that run over passages,
- Always ensure sufficient lighting (working area and passages).







The risks: relating to displacement





The risks: relating to displacement

Remember

- Understand and respect markup
- Wear suitable shoes
- Be more careful of slippery surfaces
- Ensure a good view of the traffic area
- Suitable walking speed (don't run)
- Do not leave anything in the passages





LE TOP DES INTOLÉRABLES

sur le site de Tihange

NE PAS PLACER DE PROTECTIONS EN CAS D'OUVERTURE D'UN PLANCHER OU DE RETRAIT D'UN GARDE-CORPS I

Electrabel




Awareness on safety culture, security, radiation protection and Environment


The risks relating to earthquakes















Equipments on wheels, trolleys, chests

2 wheels min. must be blocked. → → The trolleys must be equipped with wheels with brakes !



> Temporary : pincers



> Permanent : anchoring








Use of gas cylinder

- → Attached with (at least) 2 anchoring points Or
 - \rightarrow Stored in attached specific racks







Handling device

→ When not in use, Stoed in "garage position"



2 VINCOTTE

154

CONTROLATOM



Electrical rooms

- Close electrical chests
- Do not leave material or unfixed object on tables, trolleys,

Unintenional trigger of electromechanic relays (vibrations)







stocking













Awareness on safety culture, security, radiation protection and Environment

The risks relating to electricity





Causes :

Direct contact

→ Contact with conductive parts intended to conduct voltage

Indirect contact

Contact with conductive materials or substances not intended to conduct current

Consequences :

- Burns
- Fire
- Explosion
- Electrification
- Electrocution







In order to operate on an electrical installation:



Authorisation (art. 47 of the R.G.I.E.)

BA4: "Warned" person Person who is sufficiently informed or monitored by a qualified person to avoid the dangers generated by electricity

BA5: "Qualified" person Person whose technical knowledge or experience allows him to avoid the dangers generated by electricity

Send these authorisation levels to EBL!





Useful information

Intensity: ampères (A)
 Voltage: volts (V)
 Resistance: ohms (Ω)
 Power: watts (W)



- 220 V = low voltage but still dangerous !
- 24 V = very low safety voltage (TBTS) if power supply under certain conditions and skin dry

! The overheating of a wire, a motor or a device may cause a fire





8 golden rules

- 1. Prepare the "Out" work
- 2. Separate the electrical installation
- 3. Ensure no re-powering (locking/condemning)
- 4. Check the absence of voltage (check)
- 5. Ground, discharge and short-circuit
- 6. Mark and/or protect the electrical installation
- 7. Make the electrical installation available
- 8. Post-Job: Reconfigure to "In"



7



5



Awareness on safety culture, security, radiation protection and Environment

Risks relating to tools and machinery

CE





Risks relating to tools and machinery

Consequences :

- Contact with moving parts (possibility of physical injuries)
- Projection, bangs, falls, stumbling,...
- Electrification and electrocution
- Fire
- Noise, vibrations, heat,...







Risks relating to tools and machinery

REX



- On 28 March 2010 at 07h30, an agent installs a new disk
- During the start-up of the grinder, the disk explodes, projecting pieces into the air.
- Thanks to the MPI worn, the agent was not injured.
- The MPIs have shown why they should be worn.
- Before using a grinding wheel, check:
 - The expiry date
 - The state of the wheel (it must still be dry).





Beyond the red and white line →I wear the required M.P.I. and I respect the instructions displayed



VINCOTTE

CONTROLATOM



Some guidelines



- Be careful of grinders, circular saws,...
- These machines must be held in two hands
- Before leaving a machine that you have be using, it had to be stopped



- In case of specific tools: specific instructions
- Cleaning and maintenance: by a skilled and authorised person
- Securing for maintenance: locking, padlocking,...





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- **8 Industrial accidents**
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risks level

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Works with elevated risks level






Works with elevated risks level

Instruction 0101 on DDC

- Overhead (> 2m)
- With dangerous products
- In confined spaces
- With hot spots
- Under thermal stress
- Close to live high-voltage wires





- Irradiation
- Contamination
- With load lifting
- Hyper-bares
- ATEX
- Cryogenics



PREV/INSTR/301



Specificics :

- Preparation : the CdT is an **Electrabel CNT agent**
- Work opening :
 - Presence of the EBL Cdt and the SRP officer in order to realize the « ouverture de chantier en local » (= local site opening form) document
 - Installation of the work site panel by the SRP officer
- The EBL CdT visits the site daily and signs the "ouverture de chantier en local" document at each visit







Works with elevated risks level

Specific cases

- Activated charcoal filter efficiency test
- Use of elevated platforms
- Assembly and dismantling of scaffolding
- Asbestos removal or FCR
- Access to the reactor building (mode 1 and 2)

→ Specific procedures + personnel trained in this regard

Co-activity:

• risks controlled and managed via the various step of the

intervention process (coordination of the work)





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - Overhead work





Elevated risks: Overhead work

Consequences :

- Tipping
- Falling
- Falling objects
- Collision of constitutive component (platform)



Risk analysis:

- \rightarrow define the most suitable equipment
- ightarrow train the worker in its use









Elevated risks: Overhead work

Falling:Risk of falling from a height of 2 meters

Always carry out a risk analysis to select the most suitable solution.

- Give preference to collective protection above personal protection methods.
- If there is a risk of falling "without the possibility of using collective protection", a fall protection harness will be worn.






Harness: check before use

- State: harness, rope, connector and anchoring point
- Instructions for use
- ! Air anchor rod (in case of falling)
- No single worker









LE TOP DES INTOLÉRABLES

sur le site de Tihange

TRAVAILLER SANS HARNAIS DE SÉCURITÉ LORSQUE CELUI-CI EST REQUIS !



Electrabel



Overhead work

Falling objects

- Attach tools
- Helmet with chin strap
- On the floor: mark off the work area
- Limit the tools taken up








Overhead work

Ladder = means of access







Overhead work

Check the ladder before use

1. Check the general aspect


In case of defect, take the ladder out of service

2. Placement: Slope: 65-75° Exceeding of one meter. Attach the ladder

3. Use:

Only one person at a time Limit the carrying of load.

4. Storage:









If scaffolding is required: request from the EBL !

Reception by chief fitter (+SECT)


Weekly checking

Must be trained in its use

It is formally prohibited to: - Use scaffolding that has no receipt, - Modifying a scaffolding!

Culture de Sûreté v03-20140101

Aide - mémoire de l'utilisateur d'échafaudages



Avant de monter sur un échafaudage, je m'assure qu'il a été réceptionné en vérifiant le formulaire de réception.

 Je prends connaissance de la charge maximale admissible et, par le fait de mon intervention, je ne dépasse pas cette charge.


- Je ne génère pas de mouvements pouvant entraîner des surcharges dynamiques à la structure.
- Je respecte et j'utilise exclusivement les voies d'accès aux différents niveaux de l'échafaudage.
- Je ne réalise personnellement aucune modification de l'échafaudage.
- Le cas échéant, je fais appel à mon coordinateur d'échafaudages pour qu'il fasse modifier celui-ci par du personnel qualifié.
- Après modification éventuelle, je m'assure qu'une nouvelle réception est réalisée et formalisée sur le formulaire adéquat.
- 5 Je prends les mesures de prévention afin d'éviter les chutes d'objets (plinthes, filets, bacs pour les pièces etc...)
- b Je dispose toujours d'une autorisation de travail.
- b Je réalise une analyse des risques résiduels.





Scaffolding = periodic checking

- before use or re-use
- at least once a week
- whenever the resistance or stability may have been compromised




	175 186 18	S. T. C.	TZ	- 11.21	UL	221	- States and the	The second	
Electrab			Haerten			Pe	initiation	54	
No. of Concession, name	22/orla		Tauto	TDEC	ONTRO	DLE	Laska /	2 BR	
23/01/M CERTIFICAT DE CONTROLE 200 kg /m L 54									
IN'S THE REAL		FOR	MULAIRE DI	CORE OF STREET				Lipso	
• CONFORM		SE ELEMENTS		-	plate-forme, #5			10	
ACCES :	the	SOUS-LISSE :		Ø	support, planch métalique	"			
PLANCHER :		PLINTHE :			/	it			
USSE :	Ø	NOTE DE CAI	CUL (si requise)		-50			T.	
PLAN DE MONT	AGE				D = de 0,20 m	1	D		
Echafaudage	conforme à l'	ANALYSE par o	ritères liée au	x		111	0 11 1	linthe	
échafaudages	spéciaux (voir	demande)	[9					
	Aide-mémoire de l'utilisateur d'échafaudage présent Equipement MOBILE (nacelle, pont,) à proximité oui nont Consigne								
RISQUE SISMI	QUE à consid	érer (dans tou	s les cas, sauf			-		-	
RISQUE SISMIQUE à considérer (dans tous les cas, sauf cas particuliers) : Plate-forme, sol, support, plancher métallique et plinthes fixées oui non Echafaudage conforme suivant logigramme pour réception oui non									
Provide Statements					ou	non[
Si aucune con						non[Trigram	ime :	
RISQUE ELECTI Analyse imp	RIQUE (induct	tion ou contac	t) : Mettre à l	a terre l'échai		_	-	Réalisé	
 Analyse imp Présence échaf caméra 					oui			idation 🗌	
					oui	truction du ch		de la	
CONSIGNES RECT									
CONSIGNES RECU Si OUL personne nei	ES DE L'EX	PLOITATIO	N AVANT LI	MONTAGE	? OUI/N	ON			
Si OOI, personne pré	venue à la co	nduite après n	nontage : NO	DM :	? OUI / N DA	ON TE :JJ.	HEURE :		
CONTROLE INITIA	L DE CONFOI	nduite après n	nontage : NO	DM :	? OUI / N	ON TE :JJ.	HEURE :		
CONTROLE INITIA DDC pour le montage	venue à la co L DE CONFOR	nduite après n RMITE DE L'E 2000 (CHAFAUDAC	DM :	DA	ON TE :JJ.	HEURE :		
CONTROLE INITIA DDC pour le montage AGENT SRP : CONTRÔLELR DE	NOM : D	nduite après n RMITE DE L'E LOCO (BAIN N	TRIGRAM	ом : ie име :	DA	ON TE:JJ.	HEURE :		
CONTROLE INITIA DDC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR :	Nom :	nduite après n RMITE DE L'E 2000 (TRIGRAM	DM :	DA	TE :JJ.	DATE: 4	tion M	
SI OUL personne pre CONTROLE INITIA DDC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » :	Nom :	nduite après n RMITE DE L'E LOQ (DENA - Yn A-	CHAFAUDAG	ом : ie име :	DA	TE :JJ.	DATE: 2	1 21 M	
SI OUL personne pré CONTROLE INITIAL DOC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAC	Nom:	nduite après n RMITE DE L'E ROR (DRME : O	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 4	1 21 M	
SI OUL personne pré CONTROLE INITIAL DOC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAC	Nom:	nduite après n RMITE DE L'E ROR (DRME : O	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 2	1 21 M	
SI OUL PERSONNE PER CONTROLE INITIAL DDC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAC CONSIGNE DE SECT	Nome à la co LDE CONFOI : nº1.3.9 NOM :C NOM :C NOM : C RITE PARTIN	nduite après n RMITE DE L'E ROQ (QUIX YA A- DRME : O CULIERE : O G	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 2	1 21 M	
SI OUL personne pré CONTROLE INITIAL DOC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAC	Nome à la co LDE CONFOI : nº1.3.9 NOM :C NOM :C NOM : C RITE PARTIN	nduite après n RMITE DE L'E ROQ (QUIX YA A- DRME : O CULIERE : O G	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 2	1 21 M	
SI OUL PERSONNE PER CONTROLE INITIAL DDC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAC CONSIGNE DE SECT	Nome à la co LDE CONFOI : nº1.3.9 NOM :C NOM :C NOM : C RITE PARTIN	nduite après n RMITE DE L'E ROQ (QUIX YA A- DRME : O CULIERE : O G	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 2	1 21 M	
SI OUL PERSONNE PE CONTROLE INITIAL DDC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : * SECT = : ECHAFAUDAC CONSIGNE DE SECU SI NON CONFORME : Contrôle pur Semaine	Nome à la co LDE CONFOI : nº1.3.9 NOM :C NOM :C NOM : C RITE PARTIN	nduite après n RMITE DE L'E ROQ (QUIX YA A- DRME : O CULIERE : O G	TRIGRAM	DM : E AME : DAA BIP :5 4 7 N	DA	SA	DATE: 2	1 21 M	
SI OUL PERSONNE PE CONTROLE INITIAL DOC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAG CONSIGNE DE SECU SI NON CONFORME : Contrôle par Semaine Agent SRP Trigename	venue à la co L DE CONFOI : nº	RAUTE DE L'E 2001 BANA - J.M.A- DRME : O CULIERE : () G SE :	TRIGRAM	IM :	DA	SA	DATE: 2	1 21 M	
SI OUL PERSONNE PE CONTROLE INITIAL DOC Pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAA CONSIGNE DE SECU SI NON CONFORME : SI NON CONFORME : Contrôle par Semaine Agent SRP Trigramme Visa	Venue à la co LDE CONFOI 18"	RAUTE DE L'E 2001 BANA - J.M.A- DRME : O CULIERE : () G SE :	TRIGRAM	IM :	DA	SA	DATE: 25 DATE: 21 DATE: 21	1 21 M	
SI OUL PERSONNE PE CONTROLE INITIAL DOC pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAG CONSIGNE DE SECU SI NON CONFORME : Contrôle par Semaine Agent SRP Trigename	Venue à la co L DE CONFOI : aº	RAUTE DE L'E 2001 BANA - J.M.A- DRME : O CULIERE : () G SE :	TRIGRAM	IM :	DA	SA	DATE: 25 DATE: 21 DATE: 21	1 21 M	
SI OUL PERSONNE PE CONTROLE INITIAL DOC Pour le montage AGENT SRP : CONTRÔLEUR DE L'ASSEMBLEUR : « SECT » : ECHAFAUDAA CONSIGNE DE SECU SI NON CONFORME : SI NON CONFORME : Contrôle par Semaine Agent SRP Trigramme Visa	Venue à la co LDE CONFOI 18"	RAUTE DE L'E 2001 BANA - J.M.A- DRME : O CULIERE : () G SE :	TRIGRAM	IM :	DA	SA	DATE: 25 DATE: 21 DATE: 21	1 21 M	



Flocter	-1		and the second se						
Electrab	el		Haertens	65840		Pe	netatio	- 54	
No. of Concession, Name	23/01/1	1	TIEIC	TDEC	ONTRO	DLE	Losky/	m L BR	
	- Contraction	CE	RTIFICZ	DECEPTION	D'ECHAFAUI	AGE :	0.		
The second se		FOR	MULAIRE DE	RECEPTION					
IN" CONTRACTOR						11	11	Line	
CONFORM ACCES :		GE ELEMENTS		Ø	plate-forme, so support, planche métalique		0	1	
PLANCHER :	12r	PLINTHE :		Ø	marandra	L		T	
USSE :	Ø	NOTE DE CAI	CUL (si requise)		-50	专行之			
PLAN DE MONT	AGE				D = de 0,20 m		C Z		
Echafaudage échafaudage:	conforme à l spéciaux (vo	'ANALYSE par o	ritères liée au	×			- 11	Plinthe	
Aide-mémoire	e de l'utilisati	eur d'échafaud		Ø			~		
		elle, pont,) à				i non	9 00	nsigne	
RISQUE SISMI O Plate-form						1 non	7		
© Echafauda						non[
Si aucune con						_	_		
• RISQUE ELECT							-	mme :	
o Analyse imp	act échafau	dage sur DPI o	u CEI SI REOUI	a terre i echa Is	oui		-	Réalisé	
Présence échaf caméra							J va	lidation	
					oui	non		idation	
CONSIGNES RECU	ES DE L'ES	XPLOITATIO	N AVANT LE	MONTAGE	? OUL/N			-	
St OO1, personne pre	venue à la co	onduite après r	nontage : NO	DM :	DA	TE :JJ.	HEURE		-
CONTROLE INITIA	DE CONFO	RMITE DE L'E	CHAFAUDAC	<u>ie</u>					
DDC pour le montage									
AGENT SRP :	NOM : .C	PHIN R	TRIGRAM	ME: DAT	2. VI	. IA-	T		
CONTRÔLEUR DE L'ASSEMBLEUR :	NOM :	EYA A.	MEr.	504	107	NI	DATE: 4	YI an M	
« SECT » :				BIP Quilin	VI	SA XT	DATE : 2	Lill	
					VE	SA :	DATE :		
ECHAFAUDAG			and the second se						
CONSIGNE DE SECU	RITE PART	CULIERE : (y	compris éclairag	ge, encombrem	cost manual d			a lot a later	
					ac pas	sage,)			
SI NON CONFORME :	ACTION PR	ISE :							
Contrôle par Semaine	1	2	3	4					
Agent SRP Trigramme	un				5	6	7	1	
Visa	P							*	
Date	31/stin		and					-	
Conforme ?	Builden	OuiNen	Oui/Non	OuiNon	0				
		1			Oui Non	Outer		1 and the second	

Game!

Culture de Sûreté v03-





Scaffolding : specific points of attention



- Suspended
- Higher than 8m
- Mobile
- Lifting system
- Wind resistance
- Confined space
- Load > 300 kg/m²

Design calculation report


→ SECT





Mobile scaffolding

- Only on horizontal levels (max incline 1%)
- Wheels must be locked
- Presence of stabilisers
- Collective protection on all 4 sides
- Max height: 3 times the width of the support base
- Move only empty scaffolding (no person or equipment on board)
- Access from the inside (ladder and hatch)







Lift platforms

- SECT inspection obligation
- Compulsory wearing of the harness
- Used only by personnel trained and authorised by Electrabel
- → Specific works





PREV/INSTR/295



Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - Dangerous products









Arrange the products in the specific cabinets







Consequences:

- Asphyxia: Too little O₂
- Explosion and fire Inflammable products and/or too much O₂
- Corrosion
- Intoxication (poisoning)
- Pollution (environment)



A dangerous product can be harmful to health, the environment and/or safety









Risk of asphyxiation

- Normal concentration of O₂ in the air: 20 21%
- Below than: risk of asphyxiation
- Above that: increasing fire risk
 - Measurement of the concentration by SRP
 - Ventilation
 - Never rely on your sense of smell!





Risks of intoxication, acute/chronic poisoning


- Respiratory tracts: solids, liquids, gas,... (dust, gas, mist,...)
- Digestive tract: solids, liquids (dirty hands, cigarettes, food,...)
- Skin: liquids, solids,...
 (benzene, solvents,...)
 Be mindful of open wounds!





In case of professional use of this type of product: Medical examination at the start of contract and periodically thereafter!







Elevated risks - Dangerous products

Recognising them





Toxic materials

New







Corrosive materials











Explosive



Danger to

Workplaces



Toxic Harmful materials or irritating











materials

Corrosive materials

Inflammable materials

Combustive materials

Explosive materials



Culture de Sûreté v03-20140101



Elevated risks - Dangerous products

Recognising them



Health risks



CMR, toxic and respiratory risks



Pressurised gaseous materials

Workplaces



Ionising radiation



Biological risk



ATEX

Specific signaling: ADR = road transport...





Authorised on the site?

- Upon preparation of the P.P.S.S.E. :
 - List the necessary dangerous products
 - Attach the S.D.S. (Fr and Dutch)
- During the start-up meeting With the Work Supervisor
 - Check in Electrabel CMS if the dangerous products are registered and authorized
 - → Example : Aceton
- Limit the quantities

If not authorised, it is not allowed on the site!

Culture de Sûreté v03-20140101

S.D.S. : Safety Data sheet C.M.S : Chemical Management System





Elevated risks - Dangerous products

Fiche utilisateur

Fevdirad OX5 (Gel)



Risque

SDS: Safety Data sheet

User sheet

More information ?

- At the store
- Via the EBL ordering party

Protection individuelle obligatoire						
Protection de la Vue	Protection des Mains	Protection des Voies Respiratoires				
	Phrases R					
R35	R35 Provoque de graves brûlures.					
Phrases S						
\$24/25	Éviter le contac	t avec la peau et les yeux.				
S26	En cas de conta spécialiste.	En cas de contact avec les yeux, laver immédiatement et abondamment avec de l'eau et consulter un spécialiste.				
\$36/37/39	Porter un vêtem	Porter un vêtement de protection approprié, des gants et un appareil de protection des yeux/du visage.				

S45 En cas d'accident ou de malaise, consulter immédiatement un médecin (si possible lui montrer l'étiquette).

Premiers soins				
Contacts avec la peau	Oter les vêtements souillés, laver immédiatement et abondamment à l'eau, neutraliser avec une solution de bicarbonate de sodium à 5%.			
Contacts avec les yeux	Laver immédiatement et abondamment avec de l'eau pendant 15 mn et consulter un ophtalmologiste.			
Ingestion	Rincer la bouche à l'eau. Ne pas faire vomir, hospitaliser d'urgence.			
Inhalation	Amener la victime à l'air libre.La maintenir au chaud et au repos.			

Stockage - Manipulation - Environnement - Incendie

Precautions pour les personnes

Exigences relatives aux containers et zones de Polyéthylène. stockage

Procédé de nettoyage et d'absorption adéquat



Elevated risks - Dangerous products

Store them





Cabinet = temporary storage





Flammable liquids must be kept in safety drums



Caractéristiques principales :

- Pourvu d'un <u>bouchon de sécurité</u> (avec généralement un bec verseur auto-fermant).
- Récipient <u>métallique</u> (bidon ou jerrican).

L'étiquetage doit contenir les informations suivantes :

- Le nom du produit.
- Les <u>pictogrammes</u> de danger et les <u>symboles</u> d'obligation du port des MPI.
- Les phrases <u>R et S</u>.

Ces informations sont données sur la <u>fiche</u> <u>utilisateur</u> fournie au magasin et disponible sur Hazapro.





Elevated risks - Dangerous products

Store them





Elevated risks - Dangerous products

In case of splash













Remember

- Worker exposed: medical examination upon start of contract, then periodically thereafter
- Before using a dangerous product: authorised (?) and know it
- The effect of a dangerous product on a person: acute or chronic
- All containers must be labelled: name of the product, danger symbol, H & P statements (R and S phrases), manufacturer or supplier name

Dangerous product splashed onto the body: rinse thoroughly with water (min 10')

In case of a problem







Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - confined spaces





Consequences :

Asphyxia - Explosion - Electrocution - Intoxication

Safety measures :

- Measured by SRP: O₂, toxic gas, T°
- Comply with SRP instructions (break times, wear of detectors...)
- Easy access and quick exit possible
- Sufficient lighting (low safety voltage)
- Correct ventilation
- For the duration, presence of a specially trained supervisor of the confined space

PREV/INSTR/206





The term "Confined Space" refers to actual reservoirs, tanks, cavity gaps, enclosures, tunnels,...

Always work with a monitor !!!

 Take care when painting in confined spaces; the emissions are heavier than air and ventilation of the bottom levels is more difficult.

 During work: the monitor's task is to monitor the correct progress of the operations and to activate the emergency plan in case of an emergency situation. The monitoring of the environment is done by the SRP





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - hot spots - fire





MAJOR risk in a nuclear plant for safety

Work sites with hot spots require a fire permit



Electrabel

PERMIS DE FEU

Nº DDC

NUMERO D'URGENCE sur les sites ELECTRABEL : 4444

Poste Technique :				
Court texte (DDC) :				
Localisation :				
Description du travail : Meuler - disquer - souder - feu our	vert - oxycouper - chauffer - Autre			
Date de début	Durée probable des			
du permis de feu : <u>Heure</u> :	travaux avec permis de feu :			
RAPPEL : durée de validité du permis de feu maximum 24 heures				

Max 1 week





Fire Monitor : is trained and puts monitoring in place SF0 (operator) => zone with insignificant residual risk => monitors his workplace by himself

SF1 (accompagnied operator) => zone with small residual risk



=> Takes the protection steps

- evacuation of combustible material
- protection of openings with RF blanket
- handling of inflammation risk by conduction
- absence of interferences with other works

Monitoring maintained 30' after the "hot" spot





SF2 (specific supervisor)

- => zone with significant residual risk
- => operator is accompagnied by a specific trained supervisor

Ex : Work on or close to titanium (condenser pipe of unit 1)

Rem : PERMANENT monitoring, the SF does not go absent (even to monitor an other workplace, except if direct view on both).

The SF may simultaneously do other tasks as long as it does not have any incidence on the quality of the fire risk monitoring.



Electrabel

Elevated risks - Fire

Zones with residual risk	Characteristics	SF level	Training	Who is the SF ?			
Insignificant	 11m perimeter No combustible No opening No conduction No oxycutting work 	SF0	No	The operator monitors his workplace by himself			
Small	 11m perimeter No useless combustible Protected combustible materials Obstructed openings No combustible behind partition walls 	SF1	Yes	The operator is trained and accompagnied by a person who warns him in case of fire beginning (+30min)			
Significant	Other situationsTitanium	SF2	Yes	A trained supervisor is permanently present (+30min)			


Exempted zone :

These zones do not need to be monitored because these are specially made and controlled for hot spot works Ex : Welding workshop











Some important properties :

- Density :
 - Lightest: Acetylene and natural gas
 - Heaviest: Butane, Propane and fuel vapors
- Flash point:

The flash point of a volatile material is the lowest temperature at which it can vaporize to form an ignitable mixture in air.

• Autoignition temperature :

The autoignition temperature of a substance is the lowest temperature at which it will spontaneously ignite in a normal atmosphere without a flame, a spark...





Some important properties :

➔ Spontaneous combustion : wastes in dustbins












How to control the situation ?











- Fire door = always closed except when :
 - Use of a numbered wedging device
- Fire door : ensure that it is properly closed after each use







Nuclear safety

Fire-stopping







Permanent

Elevated risks - Fire


Storage of mobile thermal loads

- Respect the designated areas
- If necessary, contact your ordering party

221

CONTROLATOM

/INCOTTE







The best thermal load is the one that does not exist













Compliance

- Order and cleanliness (Housekeeping)
- Storages (delimited, time-limited, distance, screens)
- Fire permit (control, fire extinguisher)
- Waste disposal procedure (selective sorting)
- Emergency exits:
 - keep them clear!
 - Do not use them as "normal" exits

Smokers !! : only in the specifically designated areas located outside

cigarette butt in ashtray







LE TOP DES INTOLÉRABLES

sur le site de Tihange

FUMER EN DEHORS DES ZONES AUTORISÉES !



Electrabel





Your responsibility!

- Constantly monitor not create risks
- Comply with the safety instructions
- Be familiar with the workplace
- Identify the extinguishing equipment
- Be familiar with the emergency exits





What do you do if a fire has started?



If possible, intervene with the equipment available

Do not endanger yourself





Culture de Sûreté v03-20140101

VINÇOTTE ACADEMY CONTROLATOM



Act efficiently without wasting time

Do not put your life in danger

- 1 minute = a glass of water!
- 2 minutes = a bucket of water!
- 5 minutes = a tank of water!
- 10 minutes = . . .do what you can! ! !









What are the 3 sides of the fire triangle ?

a) Combustible, heat, oxygen
b) Combustible, spark, oxygen
c) Combustible, energy, combustive
d) Combustible, spark, combustive





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels


- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - thermal environment





LOCAL A CONTRAINTE





Work with elevated risks - Thermal environment

Working in a thermal environment

Measurement of the effective temperature:

WBGT index

When preparing an operation:

DDC code 0768 (heat)

contact the Intervention SRP for measures BEFORE the work.





PREV/INSTR/255



Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - Lifting and transporting of loads







Risks :

- Load falling
- Colliding with or crushing a person
- Colliding with or crushing an object
- Tipping of the equipment

Pre-requisite (security post):

- Medical fitness
- Specific training
- More than 18 years old





Storage

(garage position)

after use!





Lifting machinery and accessories

Inspection by a SECT

Trimestrial : lifting devices

TO BE CHECKED !



Ex : valid until end of april 2011

Culture de Sûreté v03-20140101

2010	GRIS	
2011	JAUNE	
2012	VERT	
2013	BLEU	
2014	POURPRE	
2015	GRIS	
2016	JAUNE	
2017	VERT	
2018	BLEU	
2019	POURPRE	
2020	GRIS	

Without "correct colour disk" marking or outside validity period

Do not use

NCOLLE

AIB CADEMY CONTROLATOM



Storage after use (storage conditions)





At the CNT




COMPULSORY





Command gestures and golden rules of lifting





Lifting machinery and cranes

If used: to be mentioned during <u>preparation</u> of the DDC

Compulsory legal inspection beforehand

Suitability for the work

Compliance with the rules of use

Attention forklift (handling)







LE TOP DES INTOLÉRABLES

sur le site de Tihange

PASSER SOUS UNE CHARGE DANS UNE ZONE BALISÉE !


Electrabel



Lifting devices

Overhead crane, gantry, arm, crane, monorail, . . .







(Overhead crane (single/double girder, one or several lifts), monorail, arm, gantry and semi-gantry)





Lifting devices

Cranes and hoists









Lifting devices

Types of control





control cubicle control level or remote control



Stored after use!







How?

Lifting

- Always comply with the lifting capacity and never overload,
- Mark out the route and prepare the unloading position,
- Make sure that no hand is exposed (maintain slings,...),
- Tauten the slings without lifting the load, allow the slinger to move far enough away,
- Gently lift the load to check correct fastening, balance and stability,
- Lift the load to transport height.
 (Keep the load as close to the floor as possible)









Positioning

Find the errors !












Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Work with elevated risks - ATEX





Elevated risks - ATEX

Explosive Atmospheres




ATEX





Elevated risks - ATEX




- **1.** Prevent the formation of ATEX
- 2. Avoid the combustion of the ATEX
- 3. Reduce the harmful effects of the explosion





Elevated risks - ATEX

Gas explosion: Gaz concentration




	LIE 96	LSE 96	den sité
Gaz naturel	4,0	15	0,55
acétylène	1,5	82	0,91
acétone	2,5	13	2,01
essence	1,4	6	3,00
but ane	1,5	8,5	2,01
propane	2,1	9,5	1,55
hydrogène	4,0	75,6	0,07
éther	1.7	40	2,60
méthanol	6	36,5	1,11
CO	12,5	74	0,97





ATEX material


- Specific material for each ATEX zone
- Placement and maintenance by qualified personnel
- Excellent grounding (To avoid static electricity)








ATEX material







ATEX zone: example







Classification of the ATEX zones

Zone ATEX	Gaz	Poussière
En permanence, longues périodes ou fréquemment	0	20
Occasionnellement en fonctionnement normal	1	21
Non susceptible en fonctionnement normal ou n'est que de courte durée	2	22





Explosive products on the CNT site

- Hydrogen: about 1,000 bottles cooling AC generator , CCV, AED tank (Ti2 + Ti3), TEG, battery rooms
- > Propane: about 10 bottles boiler ignition gas (CVA)
- > Acetylene: about 40 bottles welding workshop



> Chemical products: labs, flammable product rooms, stores





In practice

Each high-risk zone is identified on site by:



ATEX risk \rightarrow no ignition source in this area ! \rightarrow Wear of explosimeter is compulsory Check the special guidelines on the DDC

Attention to works done close to the area !







Elevated risks



List the works included in PREV/INSTR/301.





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Moyens de protection Individuelle (MPI) *Personal Protection Equipment = PPE*





MPI = Moyen de protection Individuelle

Any device or equipment intended to be worn by a person in view of protecting him from a threat to his health or his safety







MPI must:

- Be suitable without causing a new risk,
- Respond to the conditions in the workplace,

MPI

- Be compatible and maintain the efficiency of the equipment in case of multiple risks or during the simultaneous wearing of several pieces of equipment,
- Be used in accordance with with the instructions.















The employer of each company is responsible for the purchase, the supply, the maintenance, the repairs and the replacement of the MPI







Outside the zone

Clean clothes and external company

T-shirt \neq **MPI**



Culture de Sûreté v03-20140101

PPE - Standards

- 1 Casque
- obligatoire dans les locaux industriels et les chantiers
- attention : le casque est interdit en salle de commande
- 2 Lunettes de sécurité
- obligatoires dans les locaux industriels et les chantiers
- **3** Protections auditives
- respect de la signalisation
- 4 Badge
- porté de façon visible
- attention : lanyard interdit dans les locaux industriels, les chantiers et les ateliers
- 5 Gants de sécurité
- obligatoires pour toute intervention
- spécifiques à l'intervention
- 6 Chaussures de sécurité
- obligatoires dans les locaux industriels et les chantiers
- Tenue de travail hors zone
- Ie bleu de travail
- (pantalon et veste à longues manches)
- Où
- Partout hors zone dès qu'il y a intervention
- Pour qui
- Electrabel et entreprises extérieures
- techniciens d'entreprises extérieures
- ▶ autorités
- visiteurs accompagnés
- Situation exceptionnelle
- en cas de canicule, le Département Care définira la tenue





CONTROLATOM



PPE - Standards

- 1 Casque
- attention : le casque est interdit en salle de commande (TEL, TEF, ...)
- 2 Lunettes de sécurité
- **3** Protections auditives
- respect de la signalisation
- 4 Badge
- disposé dans la pochette transparente de la salopette blanche
- attention : lanyard interdit
- 5 Gants de sécurité
- obligatoires pour toute intervention
- spécifiques à l'intervention
- les mains doivent toujours être couvertes; hors
- intervention, port de gants en coton blanc
- 6 Chaussures de sécurité
- 7 Dosimètre électronique et dosimètre film badge
 - Tenue de travail en zone
- ▶ salopette blanche
- chaussettes blanches
- gants
- Où
- Partout en zone contrôlée

Pour qui

 toute personne qui entre en zone contrôlée
 excepté: en situation d'urgence pour les EPI, le SRI, le SMUR, le CBMT






Culture de Sûreté v03-20140101

P.19

In zone



Types of protection









Protection of the body

Clothes

- for working : Comfort - not floating = tight around the wrists, ankles and neck - preferably no pockets or with closed or stitched pockets - easy to wash - Esthetic
- for protection : Protection against the specific risks that the workers are exposed to







Safety hat

Compulsory in industrial rooms and on worksites



- Expiry date : see manufacturer's instructions
- Must be replaced if cracked or after impact







Glasses

- Corrective lenses possible or panoramic frames
- Replace when visibility is reduced
- NB : Glasses \neq safety glasses

Compulsory in industrial rooms, on site and in zone











Protection of the face

Face screen

Specifically indicated for work :

- above head height,
- on powered electrical installations,
- when grinding,...

Materials: polycarbonate









Protection of ears

Protection

- worn inside the ear: plugs, otoplastiques,...
- worn outside the ear: soundproof headphones, ear protectors
 - Possibility of reducing certain frequencies
 - Choice: depending on the use and the comfort of the u











Protection of respiratory tracts

Breathing device

- If harmful substances are present (solid, liquid or gas)
 - → Suitable device (concentration, intervention time,...)

• If concentration O₂ = OK AND concentration in pollutant is acceptable:

- Disposable mask,
- Half filtering mask
- Mask covering the whole face

Otherwise independent protection (outside air supply or oxygen tanks)







PPE

Protection of respiratory tracts

Breathing device

• Dust:

- P1 for inert and harmless dusts
- P2 for harmful dusts
- P3 for toxic substances and asbestos



gases & vapours:

- A brown: organic
- B grey: inorganic, acids, phosphorous hydrogen, chlorine, . . .
- E yellow: sulphur dioxide, hydrogen chloride, . . .
- K green: ammonia
- CO Black: carbon monoxide
- reactor Orange: iodine







PPE

Protection of respiratory tracts

Breathing device

	Usage a	utorisé en zone	
Modèle	lorquage	Code couleur	Utilisation
	P3 069503 11	Blanc-P3	Particules radioactives Bactéries, virus
	89 Reakton	Orange	Iode radioactif
REMARKAN	DIN 3181 T3 Reaktor P3 EN 12941 - P-SL EN 12942 - P-SL	Blanc	Particules radioactives
		Brun	Solvants
11		Gris	Vapeurs inorganiques
The second se	Ho: max, 50 h	Jaune	Anhydride sulfureux
	06950394	Vert	Ammoniaque
	00000334	Rouge	Vapeur de mercure max. 50h
		Blanc-P3	Particules radioactives

Culture d

En cas de doute, consulter un agent SRP ou consulter la notice d'utilisation du fabricant







PPE

Protection of hands

Gloves



Controlled area: permanent wearing of cotton gloves







Protection of feet

Safety shoes

Crushing, collisions, bumps, perforations,... : Work permanently



Compulsory in industrial rooms, on site and in zone

VINCOTTE ACADEMY CONTROLATOM



PPE - Standards

Site message board: obligations

Specific PPEs

Elec		N° de DDC :			Chantier :	1	-			
	trabel	EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :	
GT	of svez	BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :	
		DATE :Du	au		AGENT SRP	Nom :	Trig :		SRP :	
Mesures d'irradiation			Travail à risque élev	∕é∶O/N si oui, motif	·					
			Risques identifiés :							
Date Au poste de travail (µSv/h)										
				Consignes pour inte	ervention :					
										•••••
								•••••	• • • • • • • • • • • •	•••••
Mesure	s de contaminati	on et de sécurité a	vant ouverture	-				••••••		•••••
Date	contamination surfacique	contamination atmosphérique	sécurité (% LIE H ₂ ,% O2, T° WBGT)		••••••	••••••	•••••	•••••	• • • • • • • • • • • •	•••••
	(Bq/cm ²)	(Bq/m ³)	T° WBGT)		••••••	••••••	•••••	•••••	• • • • • • • • • • • •	••••••
	(Bq/cm²)	(Bq/m³)	T° WBGT)	-	••••••	•••••••	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
	(Bq/cm ²)	(Bq/m³)	T° WBGT)	Point d'arrêt :		· · · · · · · · · · · · · · · · · · ·	······	Levé par:	VISA:	Date:
	(Bq/cm²)	(Bq/m ³)	T* WBGT)	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·	·····	· · · · · · · · · · · · · · · · · · ·	Levé par:	VISA:	Date:
Mesure		(Bq/m³)	près ouverture	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	Levé par:	VISA:	Date:
Mesure		(Bq/m³)		Point d'arrêt :		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	Levé par:	VISA:	Date:
	es de contamination	(Bq/m³)	près ouverture	Point d'arrêt :	<u></u>	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	Levé par:	VISA:	Date:
	es de contamination	(Bq/m³)	près ouverture		<u>:ès :</u>			Levé par:	VISA:	Date:
	es de contamination	(Bq/m³)	près ouverture		:ès :			Levé par:	VISA:	Date:
	es de contamination	(Bq/m³)	près ouverture	·····	:ès : □ 🕐 🗆 🍏			Levé par:	VISA:	Date:
	es de contamination	(Bq/m³)	près ouverture	·····	<u>:ès :</u>			Levé par:	VISA:	Date:





Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

Safety signalling






Symbols and pictograms

Understand the message without knowing the language (the text is additional)







Forbidden







Obligation

Vue	Tête	Ouïe	Voies respiratoires
Pieds	Mains	Corps	Figure
Contre les chutes de hauteur	Passage pour piétons		Obligation générale (accompagné le cas échéant d'un panneau additionnel)





Warning







Safety or Emergency





Point de rassemblement



Assembly room



Vers escaliers de secours





Fire fighting


















	NE DE STOCKAGE
CHAN	TIER
Firme	•••••••••••••••••••••••••••••••••••••••
Chargé de trav	/aux Ebl
ſél/Bip	
N° DDC	
Lieu de stocka	ige
Superficie de s	stockage
Nature du ma	tériel stocké
Date de pose	du matériel
	t du matériel

* Critère au verso

Electrabel





1000 M Joules (278 kWh) équivaut à

Solides consommables	Kg	Liquides	Kg
Valeur par défaut	25	Valeur par défaut	20
Charbon actif (noix de coco)	40	Combustibles (point éclair entre 55 et 100 °c)	
Plastiques	50	Fuel, huile, graisse	25
Déchets en vrac	50	Peinture	100
Résines	50	Inflammables (point éclair < 55 °C)	
Chiffon	50	Acétylène, méthane, propane	20
Papier	50	Solvants, essence	25
Bois	50	Ether	30
		Ethanol, méthanol	40

Gaz	Kg	Bonbonnes 50l/200bars	Matériels (sauf MPI)	Pces
Valeur par défaut	10	1 pce	Valeur par défaut	1 pce
Hydrogène	10	10 pces	Appareil électrique	10 pces
Acétylène, méthane	20	3 pces	Câble électrique	100 kg
Propane	20	1 pce	Groupe mobile de ventilation/filtration (cyclair)	1 pce
Gaz naturel	25	1pce	Gaine pour cyclair	25 m
Aérosols		35 pces	Matériels MPI (yc tenue universelle de zone)	50 kg
			Engin manutention thermique/électrique	1 pce

INTERDITS				
Bois pour échafaudage (utiliser planchers métalliques)	Acétone (sauf labo)			
Bois pour planchers (utiliser plaques marquées «résistant au feu»)	WD40 (utiliser aérosol LP40)			
Plastic couvre sol sauf avec retardateur de flamme				





Electrabel

VINCOTTE

ACADEMY CONTROLATOM

Electrabel

Safety signalling



















The coexistence of 2 types of markings is not abnormal, but no marking is a mistake!





Asbestos and FCR

The places containing asbestos are identified

Asbestos inventory

Asbestos: carcinogenic product

Ceramic fibres : may cause cancer

Unauthorised operation forbidden

FCR: Refractory Ceramic Fibres



L'AMIANTE



Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- **14 Environnement**





Awareness on safety culture, security, radiation protection and Environment

FME policy






Foreign Material Exclusion

No foreign material in the systems! FME = all preventative measures to avoid compromising Nuclear Safety functions by the presence of foreign material in the installation











Zone FME

- Accès du personnel contrôlé
- Utilisation des barrières anti-intrusion
- Inspection FME en fin de chantier

Si nécessaire :

- Veilleur FME
- Inventaire matériel entrant/sortant
- Outillages attachés





• Discuss the FME risk during start

up meetings

If standard FME risk: you must

- Control personnel access
- Use FME protections (pink FME caps, FME sachets,...)
- Carry out inspections at the beginning and the end of the operation

Transparent plastic is forbidden in the controlled area





If high FME risk : in addition to the above

- Appoint a FME monitor
- Respect to the instructions of the FME monitor
- Do an equipment inventory
- Check the FME compatibility of the operators and their tools
 - Close pockets or empty them
 - Attach tools
 - Dosimeter inside
- Formalise the risk analysis
- Place a FME markup at the zone in question

Zone FME Risque Elevé

- Accès du personnel limité
- Veilleur FME
- Inventaire matériel entrant/sortant
- Outillages attachés
- Utilisation des barrières anti-intrusion
- Inspection FME en fin de chantier

















Table of content

- **1** Introduction
- 2 The nuclear powerplant
- **3 Nuclear security**
- **4 Nuclear safety**
- **5 Intervention process**
- 6 Quality assurance
- 7 Legislation
- 8 Industrial accidents
- 9 Risks
 - relating to displacement
 - relating to earthquake
 - relating to electricity
 - relating to tools and machinery

Website : http//: www.culturesurete.be

10 Works with elevated risk levels

- Overhead work
- dangerous products
- confined spaces
- hot spots and fires
- thermal ambience
- load lifting
- ATEX
- **11 Personal protection equipment**
- **12 Safety signalling**
- **13 FME policy**
- 14 Environnement





Awareness on safety culture, security, radiation protection and Environment

Environment







Basis of the SME : ISO 14001

Environmental Management System (SME)

Management policy with 3 objectives:

- **1. Respect the legislation (environmental permit)**
- 2. Environmental performance
 - Identify the impacts
 - Reduce them (continuous improvement)
- 3. Manage the relations with: the authorities, the inhabitants, the personnel and the contractors

Structure the approach

Ensure traceability

Offer credibility (via certification)









Basis of the SME : ISO 14001



Continuous improvement







EMAS


ECO MANAGEMENT AUDIT SCHEME

Our environmental policy



Déclaration de politique BU Production

Our environmental statement



Participation of all including third parties



Culture de Sûreté v03-20140101

VINCOTTE ACADEMY CONTROLATOM



priority

Environment



Manage waste

Outside the zone Triple bins

Household, Paper, Metal, Grease cloths, Aerosols, Electronic waste



Inside the zone Double bins

Combustible, Non-combustible









Manage waste





Temporary storage area







Recommendations for managing waste

Waste must be sorted directly by all (members of staff and outside operators)
The best waste is the waste that is never produced





Dangerous products

(procurement, storage and use)

Containers < 20 l

Permanent point of attention: Prevention of environmental pollution

ENV/00/012 & ENV/00/013





Dangerous products

(procurement, storage and use)

Containers > 20 l

Permanent or temporary depots:

- Classified (environmental permit)
- Register
- Compulsory signing

sinche Bepot diabbe				
Description				
PCT1-GDS 1B01FD				
Caractéristiques				
Fuel léger				
Xn, N				
Oui				
Réservoir fixe enterré				
80000				
69,2				
Non				
lisation				
PCT1-BAT-D EXT				
B007				
D047-1				
ues (SPW)				
63.12.09.03.02				
Liquides inflammables combustibles				
dont le point d'éclair est supérieur à				
55 °C et inférieur ou égal à 100 °C et				
dont la capacité de stockage est				
supérieure ou égale à 25 000 l et				
inférieure à 250 000 l				

Permis d'environnement - Dépôt classé

Service responsable



ENV/00/10



priority



Emergency situations



Everybody must:

Inform the EBL Work Supervisor









Emergency situations

 Intervene to prevent environmental damage, without endangering your life or that or others or the installations



When the situation is under control:

- Complete the "Accident environmemental" event sheet
- Submit to the Environmental Coordinator







Remember



You are responsible for your own waste and for sorting it







Where to put a beaker after use ?

a) DMC dustbin
b) Ad-hoc support
c) Dustbin for combustible material
d) Dustbin for household wastes





Electrabel

Culture de Sûreté v03-20140101

Vous

avez

l'énergie



Awareness on safety culture, security, radiation protection and environment.

Basic elements of radiation protection





At the end of this training

- I know what « radioactivity » is
- I know the different types of radiations
- I know the characteristics of radioactive sources
- I understand the interactions of radiations with matter
- I know the basic dosimetric units
- I am informed about biological effects of radiations
- I am informed about natural and artifical sources of radiations





Table of contents (1)

Basis of radiation protection

- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristics
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity





Positioning



Radiation protection

Which types of ionizing radiation do we find in a nuclear power plant ?

- A. Alpha
- **B.** Beta
- C. Gamma ray
- **D. Ultraviolets**
- **E. Neutrons**
- F. X ray
- G. Omega







Radiation protection

What is highly efficient to reduce gamma radiation ?

Positioning

A. Paper

B. Lead

C. Air

D. Aluminium





Radioactivity

Radioactivity

• Examples ... ? ?






Radioactivity

Composition of matter : atoms

- Nucleus : neutrons (neutral) et protons (+)
- Electrons (-)



CONTROLATOM

Radioactivity

	GROUPE	1	FAE	BLE	A	JP	ÉR	10	DIC	UE	ED	ES	ÉL	.ÉN	IEN	NTS	S	
	1 1.0079												10					2 4.0026
1	H					BOUDU		NUR C'RE	DU GROUPI									He
	HYDROGÈNE						TIEMICALA					13 IIIA 14 IVA 15 VA 16 VIA 17 VIIA						
	3 6.941	4 9.0122			(1985)		13 IIIA		(1760)				5 10.811	6 12.011	7 14.007	8 15.999	9 18.998	10 20.180
2	Li	Be	NOMBRE ATOMIQUE — 5 10.811 — MASSE ATOMIQUE RELATIVE (1) BCN OF									Ne						
	LITHIUM	BÉRYLLIUM	SYMBOLE B								BORE	CARBONE	AZOTE	OXYGÈNE	FLUOR	NÉON		
	11 22.990	12 24.305					BORE	NOM DE	L'ÉLÉMENT				13 26.982	14 28.086	15 30.974	16 32,065	17 35.453	18 39,948
3	Na	Mg					- 100	. [- VIIIB -				Al	Si	Р	S	Cl	Ar
	SODIUM 19 39.098	MAGNÉSIUM	3 IIIB 21 44.956	4 IVB	5 VB	6 VIB	7 VIIB	8 26 55.845		10 28 58.693	11 B		ALUMINIUM 31 69.723	SILICIUM 32 72.64	PHOSPHORE 33 74.922	SOUFRE 34 78.96	CHLORE 35 79.904	ARGON 36 83.80
4	K	Ca	Sc	Ti	V	Cr	Mn	Fe	Co	Ni	Cu	Zn	Ga	Ge	As	Se	Br	Kr
	POTASSIUM	CALCIUM	SCANDIUM	TITANE	VANADIUM	CHROME	MANGANÈSE	FER	COBALT	NICKEL	CUIVRE	ZINC	GALLIUM	GERMANIUM	ARSENIC	SÉLÉNIUM	BROME	KRYPTON
	37 85.468	38 87.62	39 88.906	40 91,224	41 92.906	42 95.94	43 (98)	44 101.07	45 102.91	46 106.42	47 107.87	48 112.41	49 114.82	50 118.71	51 121.76	52 127.60	53 126,90	54 131.29
5	Rb	Sr	Y	Zr	Nb	Mo	Tc	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Te	Ι	Xe
	RUBIDIUM	STRONTIUM	YTTRIUM	ZIRCONIUM	NIOBIUM	MOLYBDÈNE	TECHNÉTIUM	RUTHÉNIUM	RHODIUM	PALLADIUM	ARGENT	CADMIUM	INDIUM	ETAIN	ANTIMOINE	TELLURE	IODE	XÉNON
	55 132.91	56 137.33	57-71	72 178.49	73 180.95	74 183.84	75 186,21	76 190.23	77 192.22	78 195.08	79 196.97	80 200.59	81 204.38	82 207.2	83 208.98	84 (209)	85 (210)	86 (222)
6	Cs	Ba	La-Lu	Hf	Ta	W	Re	Os	Ir	Pt	Au	Hg	TI	Pb	Bi	Po	At	Rn
	CÉSIUM	BARYUM	Lanthanides	HAFNIUM	TANTALE	TUNGSTÈNE	RHÉNIUM	OSMIUM	IRIDIUM	PLATINE	OR	MERCURE	THALLIUM	PLOMB	BISMUTH	POLONIUM	ASTATE	RADON
	87 (223)	88 (226)	89-103	104 (261)	105 (262)	106 (266)	107 (264)	108 (277)	109 (268)	110 (281)	111 (272)	112 (285)		114 (289)				
7	Fr	Ra	Ac-Lr	Rf	Db	Sg	Bh	IHS	Mit	Uum	Unu	Uub		Uuq				
	FRANCIUM	RADIUM	Actinides	RUTHERFORDIUM	DUBNIUM	SEABORGIUM	BOHRIUM	HASSIUM	MEITNERIUM	UNUNNILIUM	UNUNUNIUM	UNUNBIUM		UNUNQUADIUN				A.
				Lanthanic	les													
				57 138.91	58 140.12	59 140.91	60 144.24	61 (145)	62 150.36	63 151,96	64 157,25	65 158.93	66 162.50	67 164.93	68 167.26	69 168.93	70 173.04	71 174.97
La masse atomique relative est donnée avec 6 cinq chiffres significatifs. Pour les éléments qui n'ont pas de nucléides stables, la valeur entre parenthèses indique le nombre de masse de				La	Ce	Pr	Nd	IPm	Sm	Eu	Gd	Tb	Dy	Ho	Er	Tm	Yb	Lu
			LANTHANE	CÉRIUM	PRASEODYME	NÉODYME	PROMÉTHIUM	SAMARIUM	EUROPIUM	GADOLINIUM	TERBIUM	DYSPROSIUM	HOLMIUM	ERBIUM	THULIUM	YTTERBIUM	LUTÉTIUM	
l'isote	isotope de l'élément ayant la durée de vie la lus grande.			Actinides														
Toute				89 (227)	90 232.04	91 231.04	92 238.03	93 (237)	94 (244)	95 (243)	96 (247)	97 (247)	98 (251)	99 (252)	100 (257)	101 (258)	102 (259)	103 (262)
				Ac	Th	Pa	U	Np	Pu	Am	Cm	Bk	Cf	Es	Fm	Md	No	Lr
				ACTINIUM	THORIUM	PROTACTINIUM	URANIUM	NEPTUNIUM	PLUTONIUM	AMÉRICIUM	CURIUM	BERKÉLIUM	CALIFORNIUM	EINSTEINIUM	FERMIUM	MENDELÉVIUM	NOBÉLIUM	LAWRENCIUN



Culture de Sûreté v03-20140101

Electrabel


GDF SVez




Radioactivity

Atom

Mass number (A = Z+N) Atomic number










Isotopes

 Chemical elements that have the same number of protons (Z) but differ in the number of neutrons (N=A-Z)

Example:







Radioactivity

Isotopes

• Stable or instable (radioactive)

-		0.777	+3.8		1 2701 A226	9*22. VIII	11854 1444	7 1.M22 878. 300: 465	5 COSE 1782	283, 256, 87; Treet	5° 23- 5(0173-)	145	10.546	12.07
0	NI 51	Ni 52 38.ms	Ni 53 45 ms	Ni 54 143 ms	Ni 55 209 ms	N 56 6,075 d	Ni 57 36.0 h	Ni 58 68.077	Ni 59 7.5 · 10 ² a	Ni 60 26,223	Ni 61 1,140	Ni 62 3.634	NI 63 100 a	Ni 64 0.926
		11" 10 1.34 1.96	5* 101.00	R* YHOT	8* 7.7 * 12918, 2926, 2008		17" 0.0. 7 1379, 1809.	-	EF MY ATTE	- 2.7	-23	#15	2" 0.57 50 5 9 34	
	Co 50 44 ms	Co 51	Co 52 107 ms	Co 53		Co 55 17,54 h	Co 56 77,26 d	Co 57 271,79 d	Co 58	Co 59 100	Co 60	Co 61 1.65 h	Co 62	Co.63 27.5 s
	II* II# 2,70, 2,00	-12	у" 7 800; 1526; 1947/1228	110 170 110 170	9743 940 108 9772- 148 9772-	8 ¹⁴ 1.8. 1 973, 677, 5459.	5 542 1228. 2530, 1771. 1530.		St.	+207-165	A LONG	17.1.2. 167:300	ALL STREET	17-14. 187, 982
8	Fe 49 75 ms	Fe 50 150 ms	Fe 51 305 ms	Fo 52	Fe 53	Fe 54 5,8	Fe 55 2,73 a	Fe 56 91,72	Fe 57 2,2	Fe 58 0,28	Fe 59 44,503 d	Fe 60 1,5 - 10º a	Fe 61 6,0 m	Fe 62 68 s

Carte des Nucléides, Karlsruhe





• An unstable nucleus tends to reach a stable state by spontaneously emitting radiation.

= RADIOACTIVITY

- Unstable nucleus = radioisotope or radionuclide
- Spontaneous emission= desintegration / transformation







• Radioactivity

• Types of ionizing radiations


- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity





Ionizing radiation

 radiation able to induce an <u>ionisation</u> in the matter.
 Sufficient amount of energy needs to be transferred to the bound electron in order to eject it from the atom. The atom becomes ionized.




331



Alpha

 Heavy charged particle (++), made of 2 protons and 2 neutrons, emitted by the atomic nucleus.








Beta

- Small charged particle (+ or -) that has the same mass as an electron, emitted by the atomic nucleus.
- Example :




333

CONTROLATOM



Neutron

- Uncharged (neutral) particle emitted by the atomic nucleus.
- Resulting from nuclear reactions.








Gamma and X-ray radiation

High energy electromagnetic wave (no mass, no charge). <u>Only their origin differs.</u>



Culture de Sûreté v03-20140101


CONTROLATOM

INCOTT



Gamma radiation

• Emitted by the decaying atomic nucleus.





BBture de Sûreté v03-20140101




X-ray radiation

• Produced by interactions between electrons and matter

Electronic transition

or braking radiation






X-ray

• Operating principle









- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity





The path of radiations

 Depends on number of radiation interactions with matter

→ Depends on types of radiation






The path of radiations in the air

	Туре	Path in the air
α	⁴ He	< 10 cm
β	e⁻	~ 10 m
n	neutron	~ 100 m
RX	Electromagnetic wave	few mm to 10 m
γ	Electromagnetic wave	few cm to 100 m






The range of radiations in human skin







The path of radiations in the matter








Interactions of radiation

Neutron radiation

- Efficient braking (moderation) with light target <u>Example</u>: Hydrogen atom
- Activation of matter :








Don't forget !

- Radioactivity
 - An unstable atomic nucleus spontaneously emits particles or energy to reach a stable state.
- Types of radiation
 - Alpha, Beta, Neutron, Gamma, X ray
- Interaction of radiations with matter RAY
 - Depends on type of radiation





- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity



Positioning





Radiation protection

Which unit is used to quantify the activity of a radiation source ?
A. Becquerel
B. Gray (Gy)
C. Sievert (Sv)
D. Ampere (A)









Radiation protection

The radioactive period is the time after which :

- A. The activity of a source is reduced by half
- **B.** The source is no more radioactive
- **C.** We can take the source in hands





Characteristics



1. Activity

= number of nuclei that are transformed (decay) per second.

Unit : Becquerel (Bq) = 1 decay/sec (old unit : Curie : 1 Ci = 37 GBq)

Examples :

- human body (natural C-14 and K-40) \sim 6 000 to 8 000 Bq
- administration of isotopes in nuclear medicine ~ 370 000 000 Bq
- used fuel assembly \sim 10 000 000 000 000 000 Bq





1. Activity

• We can also talk about

	Example	Example in Tihange power plant				
Volume activity	Seawater :	Tritium rejection limit in Meuse :				
	10 to 15 Bq/l	74 Bq/l				
Mass activity	Potato : 100 to 150 Bq/kg	Co-60 limit for exit of controlled area : 100 Bq/kg				
Surface activity	Contamination limit controlled area :	for exit of equipment from the				
	1 Bq/cm ² for beta/gamma					
	0,1 Bq/cm ² for alpha					

350

CONTROLATOM





Characteristics

CONTAMINATION SURFACIQUE TRANSFERABLE Emballage Bq/cm² Contenu Bq/cm² AMBIANCE / CONTACT Ie µSv/h VISA

Examples in Tihange power plant ...

- Labelling of (potentially) contaminated mobile equipment according to its activity.
- Chek of staff and equipment before leaving the controlled area. The exit is authorized or not, according to the activity.










2. Half life T¹/₂ or radioactive period

= The time it takes for half of the radioactivity to disappear.

Examples:

Tritium (H3)	12,3 years
Cesium 137	30,2 years
Iodine 131	8 days
Strontium 90	28,1 years
Cobalt 60	5, 3 years
Uranium 235	704 million years
Uranium 238	4,5 billion years





- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity





Game

Radiation protection

According to legislation, who may enter a controlled area?

A. Everybody with company authorization.

Positioning

- B. People who have been informed of the dangers of ionizing radiations and have passed a medical examination allowing them to the exposure to ionizing radiation
- C. Anyone who's followed a training and succeed the examination
- D. Everybody except women







Radioprotection

For individuals who are professionally exposed, what is the (legal) dose limitation on twelve months rolling period ?

Positioning

A. 2 mSv
B. 10 mSv
C. 20 mSv
D. 50 mSv







Radiation protection

What means the numbers which are displayed on my dosimeter?

A. The activity of radioactive source near me.
B. The activity of source which I ingested.
C. Equivalent dose
D. Effective dose
E. The time I still have to finish my work

Positioning


E. The time I still have to finish my work






Dosimetry

• Aim : to calculate the absorbed dose and to evaluate the biological effects of radiation.










Analogy








Physical quantity !

Energy absorbed per unit mass → Absorbed dose (Gray = 1 J/kg) = Deposited energy






B5 ture de Sûreté v03-20140101



Biological quantity !

Biological effects depend on the properties of the ionisation radiation (type, energy, ionisation power)










Biological quantity !

Biological effects depend on the type of the irradiated tissue or organ

→ Effective dose (whole body) (Sievert) :

= Weighted sum of the equivalent dose







In practice :

- Unit :
 - Sv = very big unit
 - mSv = 0,001 Sv
- Dose rate = dose/time
 - mSv/h ou µSv/h

Example :

The dose rate in the local is 100 μ Sv/h. If I stay one hour \rightarrow I have received 100 μ Sv

If I stay 15 minutes ?



 $0,011 \text{ mSv} = 11 \mu \text{Sv}$







Message board (in controlled area)

		N° de DDC :			Chantier :					
Electrabel		EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :	
	DF Svez	BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :	
G	OF JUCZ	DATE :Du	au	2007.2.	AGENT SRP	Nom :	Trig :		SRP :	
		**	uu	Travail à risque élev						
Mesures d'irradiation				Travail à risque élevé : O / N si oui, motif :						
Date		Au poste de travail								
Date		(µSv/h)								
				Consignes pour intervention :						
						•••••		•••••		
									· · · · · · · · · · · · · · ·	
Mesure	es de contamination	on et de sécurité a	vant ouverture			•••••				
Date surfacique atmos		contamination	sécurité	52, 						•••••
Date	(Bq/cm ²)	atmosphérique (Bq/m ³)	(% LIE H ₂ ,% O2, T° WBGT)	••••••	••••••	•••••		•••••	• • • • • • • • • • • • •	
Date	(Bq/cm ²)	atmospherique (Bq/m ³)	(% LIE H ₂ ,% O2, T° WBGT)		•••••••	•••••••••••••••••••••••••••••••••••••••			· · · · · · · · · · · · · · · · · · ·	
Date	(Bq/cm²)	atmospherique (Bq/m ³)	(% LIE H ₂ % O2, T° WBGT)	Point d'arrêt :		· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:
Date	(Bq/cm ²)	atmospherique (Bq/m³)	(% LIE H ₂ ,% O2, T° WBGT)	Point d'arrêt :				Levé par:	VISA:	Date:
	(Bq/cm²)	(Bq/m ³)		Point d'arrêt :		· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:
	(Bq/cm²)	(Bq/m ³)		Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:
	(Bq/cm²)	(Bq/m ³)		Point d'arrêt :	······	· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:
Mesure	(Bq/cm²)	(Bq/m³)	près ouverture	·····		· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:
Mesure	(Bq/cm²)	(Bq/m³)	près ouverture	·····				Levé par:	VISA:	Date:
Mesure	(Bq/cm²)	(Bq/m³)	près ouverture	·····				Levé par:	VISA:	
Mesure Date	(Bq/cm²)	(Bq/m³)	près ouverture sécurité (% LIE H ₂ ,% O2, T° WBGT)	·····				Levé par:	VISA:	Date:
Mesure Date	(Bq/cm²)	(Bq/m³)	près ouverture sécurité (% LIE H ₂ ,% O2, T° WBGT)	·····				Levé par:	VISA:	

363



Dose limitation (RD 20/07/2001)


- Whole body dose :
 - Public : 1 mSv/year





- Person professionally exposed (PPE) :
 20 mSv/12 months (twelve months rolling calender)
- Skin, hands, each organ distinctly (PPE):
 500 mSv/year









Dose limitation (RD 20/07/2001)

Organ or tissue	PPE	Public
whole body	20 mSv	1 mSv
cristalline lens	150 mSv 20 mSv ?	15 mSv
skin	500 mSv	50 mSv
hands, fingers, organs	500 mSv	-
Period	12 m	year





Dose limitation (RD 20/07/2001)

Fetus (futur baby) protection :

As soon as possible :

OPTIMISATION + max. 1 mSv during the rest of pregnancy




+ avoid the contamination risks.







Dose constraint for Electrabel (12 csm)



U



Don't forget !

- Characteristics of radioactive source
 - Activity (Bq) Radioactive period
- Doses
 - Absorbed (Gy)
 - Energy per mass unit
 - Equivalent (Sv)
 - Take into account the type of radiation and its energy
 - Effective (Sv)
 - Take into account of type the radiation, its energy and tissues damaged
 - Limits : 20 mSv/12 m (10 at CNT)





- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity







Biological effects

Impacts of radiation on DNA

- Single or double-strand breaks
- DNA repair mechanisms









Radiation effects on body : high doses

- Short term effects
 - Existence of a threshold dose
 - Severity increase with the dose
 - All exposed persons are affected

Examples : Radionecrosis (25 Gy), Gastrointestinal syndrome (> 6 Gy), ...








Relation dose - effect

• Can we predict the effects for very low doses ?



373

CONTROLATOM

BZBture de Sûreté v03-20140101



Radiation effects on body : low doses (or ow dose rates)


- Short term effects
 - No threshold
 - Probability increased with the dose
 - random
- Cancer risks
 - Repairs should be taken into account
 - Mortality risk by cancer (most pessimist case):
 - 5% per Sv for public
 - 4% per Sv for workers (18 to 65 years)





Biological effects

Model for relation dose - effect





BZBture de Sûreté v03-20140101




- Radioactivity
- Types of ionizing radiations
- Interaction of radiations
- Characteristic
- Dosimetry
- Biologicals effects
- Natural and artificial radioactivity






Both the natural and the artifical radionucleides contribute to human exposure : 4.2 mSv/year



377

CONTROLATOM








Telluric radiation (9%, 0.4 mSv)

- Sedimentary rocks : 400 Bq/kg
- Granitic Rocks : 8 000 Bq/kg
- Bricks: 800 Bq/kg
- Building products : ~ 15 Bq/m³
- ⁴⁰K, ²³⁸U, ²³²Th








Radon (32 %, 1.45 mSv (+ thoron))


Average concentration of radon in Belgium
 ~ 50 Bq/m³ in the building






Natural and artificial radioactivity

Medical applications (43%, 1.95 mSv)










Diagnostic



Natural and artificial radioactivity

Other human activities (1%, 0.05 mSv)



382

CONTROLATOM

VINCOTTI



Natural and artificial radioactivity

Use of radioisotopes

• Jauges

(level, thickness, density, humidity ...)

- Fire detectors
- Tracers (agricultural industry, operation ...)
- Research
- Lightning rod
- Irradiation (food, medical)
- Medical (diagnostic, treatment)
- Dating












Don't forget !

- Biological effects
 - High doses: short term effects (always)
 - Low doses: long term effects (probability)
- Radioelements : naturals artificials











Awareness on safety culture, security, radiation protection and environment.

Basis elements of radiation protection

SUMMARY – TO RETAIN





1. What is the characteristic of a radioactive nucleous ?





1. What is the characteristic of an radioactive nucleous ?

• An unstable atomic nucleus emitting (spontaneous) particles or energy to reach a stable state.







2. Which types of ionizing radiation we could find in nuclear power plant ?





2. Which types of ionizing radiation we could find in nuclear power plant ?

- Alpha
- Beta
- Gamma
- Neutrons
- X ray







3. What is most efficient to reduce gamma radiation ?

- Paper ?
- Lead ?
- Air ?
- Aluminium ?





3. What is most efficient to reduce gamma radiation ?

- Paper
- Lead
- Air
- Aluminium







4. Which unit is used to quantify the activity of radiation source ? And for surface contamination ?





4. Which unit is used to quantify the activity of radiation source ? And for surface contamination ?

- Activity unit is Becquerel (Bq)
- Surface contamination unit is (Bq/cm²)

~	CONTAMINATION SURFACE	1 Bq/cm ²
		IE 24/12/09
	μ S v/h	VISA







5. In the nuclear power plant, how can I measure the radiation impact on me?





5. In nuclear power plant, how can I measure the radiation impact on me?

- Electronic dosimeter
- Passive dosimeter (OSL)









6. What is the long-term risk associated to an repeated exposition to low doses ?

- Very high risk of developing a cancer before 50 years old.
- 50 % chance to die due to the consequences of irradiation.
- Skin burns.
- Risk of developing a cancer (small compared to the number of spontaneous cancers)





Questions


7. Where do we find ionizing radiations ?





Questions

7. Where do we find ionizing radiations ?





399



Awareness on safety culture, security, radiation protection and environment.

Principles and means in radiation protection





At the end of this training :

- I know the risks in controlled area
- I can apply ALARA procedure
- I know the signalling in controlled area
- I'm informed about protection means in controlled area
- I'm informed about dosimeter





Principles and means of radiation protection

- Risks in controlled area
- Justification Dose limits Alara
- Signaling in controlled area
- Means of protection in controlled area
- Dosimeter





Risks ?

Irradiation be in presence of radiation




Contamination be in contact with radioactive matter








Irradiation






Unsealed source (water)

Sealed source







405

CONTROLATOM

/INCOTT





Alpha risk

a Risk ⇔ Atmospheric contamination > 1 LDCA Example: LDCA (Am-241) = 0,2 Bq/m³

LDCA : limite dérivée de concentration dans l'air

→ *Increased care is needed* (risk of internal contamination !)

- Protection measures (masks, gloves, ...)
- Nose blow









Don't forget !

- Irradiation risks
- Contamination risks
- We can be contaminated by : ingestion, inhalation, cutaneous absorption
- In the case of injury : You must always ask at medical centre at Tihange (agreement) before entering to the controlled area.





Principles and means of radiation protection

- Risks in controlled area
- Justification Dose limits Alara
- Signaling in controlled area
- Means of protection in controlled area
- Dosimeter





Incident : of 5 octobre 2008 arround 15h00

circumstances :

leaving of skimming filter of reactor pool BR Ti1 for transfer to the shielded container, **Sequence of events**:

- During rise of filter , still underwater

 measure of dose rate : NTR
- Once the filter is out of water, SRP measures a dose rate at 1 m of filter of 15 mSv/h
 Stop : back down the filter underwater (retreat solution ?)
- Bridgeman follows SRP clears the dose rate alarm of all dosimeters which have been switched to alarm next to the pool.
- During this event, one of bridgeman assistants gets the filter out of the pool, disassociates it from the handling equipment and transports it by hands to a shielded container.







dosimetric consequences :

- Abnormal exposition of one bridgeman assistant
- Dosimetry of assistant # 1

6140 µSv (electronic dosimeter)

Dosimetry of assistant # 2

3315 µSv (electronic dosimeter)

 The legal limitation of dose is not exceeded (20 mSv/12 m), nor the CNT constraint (10 mSv/12 m).





Anomaly detected : human aspects

Two main rules of radiation protection have been violated :

o Omission of **SRP instructions** present during the manipulation,

o Pursuit of activities despite the **alarms** of the electronic dosimeter.





Basis of radiation protection

- Justification
- Doses limitation
- ALARA





Justification

Any practice using ionizing radiations must be beforehand justified by the economic, social or other advantages with respect to the health detriment that they are likely to cause.





Doses limitation

Constraints in the NPT : 10 mSv/12 c.s.m.

Period	Dose limits (µSv)
Day	Depends on job/work site access code
Week	2 000
Month	4 000
3 months	6 000

Alarms on the electronic personnal dosimeters

- Dose and dose rate
- Adapted following the intervention (Access authorization « job » or « worksite »)





Justification – dose limit - ALARA

A L A R A = <u>A</u>s <u>Low A</u>s <u>R</u>easonnably <u>A</u>chievable



= optimisation

= To take the smallest dose !

Examples of practical application of ALARA principle ???








The ALARA approach in the NPT :

Preparation of an intervention in the controlled area = dosimetric estimation !





How to know the ambiant dose rate in a local ?

➢ Files are available at the <u>SRP local</u> with the list of locals, ambiant dose rate and color code.





> On the local doors in the controlled area










Evaluation of the ALARA level

Tableau ALARA - Unité en révision






Evaluation of the ALARA level

ALARA level depends on the running phase of the installation !

Tableau ALARA - Unité en fonctionnement (hors AT)





The access code to the controlled area depends on the ALARA level

- Acces authorization « **Job** » (ALARA 0)
 - Set the daily dose limitation per job
 - For routine interventions
 - Codes are displayed on controlled area entrance



Â	Toute utilisation d'un autre numéro que o devra faire l'objet d'une autorisation préa	
N°	Autorisations "Métier"	Limite journalière (
3001	Operations - Exploitation	20
3002	Operations - Chimie	20
3003	Operations - Déchets	20
3004	Operations - Support	20
3005	Operations - GAP Révisions	20
3006	Operations - Formation	20
3007	Maintenance - Gestion des révisions - 0 GRP	20
3008	Maintenance - Housekeeping - 0HK	20
3009	Maintenance Mécanique - 0MG	20
3010	Maintenance Mécanique - 0MDP	20
3011	Maintenance Mécanique - 0MT	20
3012	Maintenance Mécanique - 0MSE, 0MSP, 0MSM	20
3013	Maintenance Robinetterie - 0 VM	20
3014	Maintenance Robinetterie - 0 VE, 0 VI	20
3015	Maintenance Robinetterie - 0 VAS. 0 VAI	20
3016	Maintenance Robinetterie - 0 VAP, 0 VAR	20
3017	Maintenance E&I- 0EE. 0ED	20
3018	Maintenance E&I- 0 EL	20
3019	Maintenance E&I- 0IT, 0IR	20
30 20	Maintenance E&I- 0IC. 0IP	20
3021	Maintenance - Mécanique Tranche	20
3022	Maintenance - Electricité Tranche	20
3023	Maintenance - Instrumentation Tranche	20
3024	Engineering	20
3025	CARE SRP	20
3026	CARE Environnement	20
3027	CARE Sureté nucléaire	20
3028	FUEL	20
3029	PPM	20
30 30	Cadres et Direction	10
3031	TC - Communication - Informatique - 0 QP	10
30 32	Zones surveillées (hors zone)	5
3051	Visites	5
3052	Bel V	10
3053	Laverie	10
3054	Nettoyage	20
3055	Atelier de décontamination	20
3050	Divers	5



Electrabel

Access authorization
 « job » (ALARA 0)

	Toute utilisation d'un autre numéro que ceux m	entionnés ci-dessous
	devra faire l'objet d'une autorisation préalable	de la SRP (via DDC)
N°	Autorisations "Métier"	Limite journalière (µSv)
3001	Operations - Exploitation	20
3002	Operations - Chimie	20
3003	Operations - Déchets	20
3004	Operations - Support	20
3005	Operations - GAP Révisions	20
3006	Operations - Formation	20
3007	Maintenance - Gestion des révisions - 0 GRP	20
3008	Maintenance - Housekeeping - 0HK	20
3009	Maintenance Mécanique - 0MG	20
3010	Maintenance Mécanique - 0MDP	20
3011	Maintenance Mécanique - 0MT	20
3012	Maintenance Mécanique - 0 MSE, 0 MSP, 0 MSM	20
3013	Maintenance Robinetterie -0VM	20
3014	Maintenance Robinetterie -0VE, 0VI	20
3015	Maintenance Robinetterie -0VAS, 0VAI	20
3016	Maintenance Robinetterie -0VAP, 0VAR	20
3017	Maintenance E&I-0EE, 0ED	20
3018	Maintenance E&I-0EL	20
3019	Maintenance E&I- 0IT, 0IR	20
3020	Maintenance E&I-0IC, 0IP	20
3021	Maintenance - Mécanique Tranche	20
3022	Maintenance - Electricité Tranche	20
3023	Maintenance - Instrumentation Tranche	20
3024	Engineering	20
3025	CARE SRP	20
3026	CARE Environnement	20
3027	CARE Sûreté nucléaire	20
3028	FUEL	20
3029	PPM	20
3030	Cadres et Direction	10
3031	TC - Communication - Informatique - 0 QP	10
3032	Zones surveillées (hors zone)	5
3051	Visites	5
3052	Bel V	10
3053	Laverie	10
3054	Nettoyage	20
3055	Atelier de décontamination	20
3050	Divers	5


ACADEMY

CONTROLATOM



The access code to the controlled area depends on the ALARA

- Access authorization « Work site » (ALARA 1 to 3)
 - Set the limit according to the intervention
 - For all interventions needing highest dosimetry level than those of routine works.
 - Attributed by SRP
 - Codes are not displayed on controlled area entrance but on the DDC. (DDC = Work permit / Work Clearance Application) <u>Remark</u>: ALARA level 2 or 3 = High risk work !





ALARA monitoring : to be filled for every ALARA 1, 2 or 3 worksite

	T3 (*)		EN A.T. :				LOCAL :			_		DATE : _	/	/		PAGE :	
JC:		-	LIBELLE	INTERV	ENTION :												_
A			4.2				Taulau			a da aire	átria TO		A 6				-
A CO	mpléter a	u tur e	ta mes	ure des	acces/s	sorties -	i oujou	rs bien	suivrei	a dosim	etne TO	TALE	N	veau: A	ALARA 1 - A	LARA 2 - ALA	RA
OSE RI	EPORTÉE (V	OIRPA	GE PRÉCÉD	DENTE) E N	Hµ SV	⇒ ⇒	⇒⇒	⇒⇒	⇒⇒	⇒⇒∍	* * *	⇒					
	· · · · ·							ENT	RÉE	SO	RTIE	DELTA	\$				
FILM	NOM PRÉNO	M					FIRME	HEURE	DOSE		DOSE		s.	TYPE DE	TRAVAIL EFFE	CTUE	
													۰.				
													÷				
													÷				
													s				
													ъ.				
													÷				
													۰.				
													8				
													a.				
													-				
													÷				
													÷				
													ъ.				
													a.				
													-				
													÷				
													÷				
													s.				
													ъ.				
													÷				
													۰.				
													ъ.				
6 % DE L	A DOSE EST	IMÉE =		HµS∨		NOUV. SEUIL	A GEN	TSRP	CHEF DE	TRAVAUX	SOMME		₹		· · · · ·		
POIN	T DOGRIPEÊTE	POLER	CHARGE	DESTRA			TRIG.	VISA	TRIG.	VSA	TOTAL H	luSv					
	L AGENT S		Jurete	voj-20	1.40.10	L					(à reporte						
											(a reporte						

Electrabel

ALARA monitoring : How to fill it correctly ?

	T1 - T2 -	al ine aire al ile a		: OUI / NO			LOCAL :					DATE:_	/	/	-	PA	GE :
	A co	moléter au fur e	etàmes	ure des	accès/s	sorties -	Touiou	rs bien s	suivre l	a dosim	étrie TO	TALE		veau : Al	ARA 1 -	ALARA	2 - AI ARA 3
	DOSE RI	EPORTÉE (VOIRPA	GE PRÉCÉ	DENTE) E N	HµSV	⇒ ⇒	⇒ ⇒	⇒ ⇒	⇒ ⇒	⇒ ⇒ =) = =	⇒		\mathbf{D}			
t					-			ENT			RTIE	DELTA					
F		NOM PRÉNOM						HEURE	DOSE	HEURE		(µ\$v)	*	TYPE DE T	RAVAIL EFF	ECTUE	
	007	Paul Dumont						08:30		09:30		45	45				-
	118	Bernard Lerr						08:30		09:30		55	100				8
	034	Jacques Mar	tinez					08:30		09:30	40	40	140				- / 7
	234	Jean-Pierre l	aroque	e			PWR	08:30	1	09:30	33	32	17,2				
									<hr/>				J.				
													J.				
ŀ	3)							4		1 5		6	h				
									\nearrow								
									-				л. Д				
ŀ													, ř				
ŀ													о Д				
ŀ													-				
ŀ													*				
ŀ															\checkmark		7
ŀ													*				
-														DT	\mathbf{c}		
-														KI	GUI		
1																	
	\rightarrow												÷		A		
	2)												ۍ				
		Exemple: d	ose es	timée =	= 240								ð.			<u>▼</u>	
	75 % DE L	A DOSE ESTIMÉE =		 ΗμSν		NOUV. SEUIL	AGEN	TSRP	CHEF DE	TRAVAUX	SOMME		₽ 5 Ø				
		T D(ARIRÊ(T@POKAR)	CHARGE	VIDE STRAN		02012	TRIG.	VISA	TRIG.	VSA	TOTAL H	lµSv	172				
		L AGENT SRP	Junete	105 20	1010						(à reporte		1/2				
																ACADEMIT SON	



ALARA report (p.1 and 2) for every ALARA 2 or 3 worksite

DOSSIER ALARA

N° du dossier ALARA :...

Dénomination de l'intervention :	

Unité : Ti1 / Ti2 / Ti3

Local :

DDC	¢O	n	e:	rn	ée ((s)	:.											 														
		• •	• • •	• • •	•••	• • •		•••			• • •			•••				 			•••	• •								• • • •		
		• •	•••	• • •	•••	• • •	•••	• • •		• • •	• • •		•••	•••	• • •	•••		 			•••	• •			•••			• • •		• • • •	•••	
		•••	•••	• • •	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	• • •	•••	•••	 •••	•••	•••	•••	•••	• • •		•••	•••	•••	• • •		• • • •	•••	
		•••	•••	•••	•••	• • •	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	 •••	•••	•••	•••	•••	• • •		•••	•••	•••	•••			•••	
	••••	••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	 • • • •	•••	•••	•••	•••	• • •	• • • •	•••	•••	•••	•••		• • • •	•••	
		•••	•••	•••	•••	• • •	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	 • • • •	•••	•••	• • • •	•••	• • •		•••	•••	•••	•••	• • • •	•••	•••	
		•••	•••	•••	•••	• • •	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	•••	 • • • •	•••	•••	• • • •	•••	• • •		•••	•••		•••	• • • •	•••	•••	
Char	gé	(s)	d	e 1	tra	va	ux	:										 														

Tel/bip contact SRIFTURE de Sûreté v03-20140101

Tel/Bip :....

PARTIE « PREPARATION »

Réalisée le .../..../..... par:

Préparateur ou chargé de travaux :..... Responsable ou agent SRP :.....

Annexes, références et REX :.....

.....

1. CALCUL DE	LA DOSE COLI	LECTIVE BRUTE		
Débit de doses (µSvh)	X Durée (h)	X Nombre d'intervenants	=	Estimation dosimétrique (Ημδν)
NIVEAU ALARA : A	LARA 2 – ALAR	A3		

2.	MOYENS DE REDUCTION DE LA	DOSIMI	TRIE		
		OUI	NON	NA	Référence Annexes/remarques
1	Organisation du travail				
	 Zone à bas ddd définie (les sas, préparation outils, information des exécutants, discussion travaux, etc.) 				
	 Préfabrication possible 				
	- Surveillance dosimétrie en local Emegistrement des doses individuelles et comptabilisation de la dose collective				
2	Aspects radiologiques				
	 Blindage (S cm PB > 1/10 & 2 S cm Pb > 1/3, la réduction de dose suite au blindage doit être plus importante que la dose pour placer le blindage) 				
	- Circuits remplis (système de blindage)				
	- Décontamination préliminaire				
	- Circuits nincés				
3	Formation des intervenants				
	- Formation ou information requise				
	- Entrainement sur maque tie				
4	Autres :				

3. CALCUL DE LA DOSE COLLECTIVE NETTE									
Débit de doses (µSvh)	X Durée (h)	X Nombre d'intervenants	=	Estimation dosimétrique (HµSv)					
NIVEAU ALARA : ALARA 1* – ALARA 2 – ALARA 3 *le dossier ALARA reste d'application									



ALARA report (p.1 and 2) for every ALARA 2 or 3 worksite

PARTIE « SUR CHANTIER »

Vérification réalisée en local le// àh par :
Préparateur ou chargé de travaux :
Responsable ou agent SRP :

	 Lorsque requis dans la partie « PREPARATION », LES MOYENS de réduction de la dosimétrie suivants SONT MIS EN PLACE : 											
3	ONT HES EN FLECE .	OUI	иои	NA	Remarques / Actions prises							
1	Organisation du travail											
	 Tone à bas ddd définie (les sas, préparation outils, information des exécutants, discussion travaux, etc.) 											
	 Préfabrication 											
	 Surveillance dosimétrie en local Enregistrement des doses individuelles et comptabilisation de la dose collective 											
2	Aspects radiologiques											
	 Blindage (5 cm PB > 1/10 & 2.5 cm Pb > 1/3, la réduction de dose suite su blindage doit être plus importante que la dose pour placer le blindage) 											
	- Circuits remplis (système de blindage)											
	 Décontamination préliminair e 											
	- Circuits rincés											
3	Formation des intervenants											
	 Formation ou information requise 											
	- Entrainement sur maquette											
4	Autres :											

2. VEFICATION DE L'ESTIMATION DOSIMETRIQUE					
Débit de doses (µ.Sv/h)	X Durée (h)	X Nombre Čintervenants	=	Estimation dosimétrique (HµSv)	
NIVE AU AL ARA : AL ARA 1 - AL ARA 2 - AL ARA 3					
CONFORME PAR RAPPORT A L'ESTIMATION ? OUI - NON					
- Si oui, le chantier peut démarrer conformément aux consignes					
- Si non, contacter un responsable SRP avant de démarter le chantier					
COMMENTAIRES ET CONSIGNES SUPPLEMENTAIRES AGENT SRP :					
Culture de Sûreté v03-20140101					
I					

PARTIE « APRES LE CHANTIER – REX»

D (Analyse réalisée le// par :
Préparate	ur ou chargé de travaux :		
Kesponsa	ble ou agent SRP :		
1. Do:	imétrie finale		
Dosimétr	ie collective	HμSv	
•	En 'préparation'		
•	Sur chantier		
•	Dosimétrie réellement prise		
DEPASS	EMENT ESTIMATION > 25	% ? : OUI -	NON
<u>Si oui</u> , ex	plications concernant le dépass	ement :	
	Temps de travail:		
	Débit de doses en local :		
	Nombre d'intervenants :		
	Autres :		
2. Poi	nts à prendre en considération	ı pour une p	prochaine intervention : OUI – NON
<u>Si oui</u> , le:	squels :		
	Temps de travail:		
	Débit de doses en local :		
	Nombre d'intervenants :		
_			
	Aléa techniques rencontrés :		
	Autres :		



Don't forget !

- Respect of the SRP instructions if dosimeter alarm
- Basis principle of radiation protection :
 - Justification dose limits Optimisation (ALARA)
- Working in controlled area :
 - Realize a dosimetric estimation
 - ALARA monitoring if necessary





Table of contents (2)

Principles and means of radiation protection

- Risks in controlled area
- Justification Dose limits Alara
- Signaling in controlled area
- Means of protection in controlled area
- Dosimeter





Warning signs - Tihange



Presence of ionizing radiations

Ionizing radiation < 20 μSv/h

Ionizing radiation > 20 μSv/h

High intensity of ionizing radiation > 200 μSv/h

P.34

Very high intensity of ionizing radiation > 1000 µSv/h Accès local rouge ddd > 1000 μ Sv/h

ВР

S

Consignes d'accès selon procédure RP/ALARA/01 Formulaire à compléter Appeler SRP pour ouverture/fermeture





Signaling in controlled area

Hot spot



If the dose rate upon contact > 1 mSv/h

Don't stay close to the hot spot











Indications on doors in controlled area





Entry and exit in controlled area







Mobile equipment

	CONTAMINATION SURFAC Emballage Contenu	Bq/cm ²	CONTAMINATION
	AMBIANCE / CONTACT	le	
	μ S v/h	VISA	
	IRRADIATION		
Culture de Sûr	eté v03-20140101		433



Entry to worksite with risk of contamination



- bench
- mark up
- stock of overshoes
- dustbins







Bench in controlled area

New situation:

- Dustbins in work area
- Feet and hands detector (SRP evaluation)
- Only one acces
- Site messages board is VISIBLE



- New bench in controlled area with :
 - Instructions on how to pass it
 - Could contain the overshoes, site message board and mark up (red and white)








Entry to clean area

No contamination



Potential contamination




- bench
- mark up
- stock of overshoes
- dustbins





Bench in controlled area : the proper way

notices (on the bench) explaining how to put the overshoes when you pass the bench




It is forbbiden to put your feet on the bench





Bench in controlled area : the proper way

notices (on the bench) explaining how to take off the overshoes when you pass the bench







Don't forget !

Signaling :

- Color codes
 - green : $< 20 \ \mu Sv/h$
 - yellow: 20 200 µSh/h
 - orange: 200 1000 µSv/h
 - red: > 1000 µSv/h

Ionizing radiations < 20 μSv/h

Ionizing radiations > 20 μSv/h

High intensity of ionizing radiations > 200 µSv/h

Very high intensity of ionizing radiations > 1000 µSv/h

- Entry and exit for persons and equipment
- How identify the labelling
- Compliance with the bench in controlled area





Principles and means of radiation protection

- Risks in controlled area
- Justification Dose limits Alara
- Signaling in controlled area
- Means of protection in controlled area
- Dosimeter





\checkmark Elimination of the source – of the danger

✓ Collective protection

✓ Individual protection

 \checkmark Evaluation of the exposure

✓ Management of the effects





Risks ?

Irradiation be in presence of radiation



Contamination be in contact with radioactive matter





Positioning





Radiation protection

How to limit the risk of irradiation?

- A. By approching the source
- **B.** By working more slowly
- C. By covering the source with a lead shielding
- D. By protecting my ears





Source "elimination"- danger elimination





Dose rate control

Elimination of contamination





Contamination – collective protection : cyclairs





Culture de Sûreté v03-20140101



Inside the work site : aspiration





Contamination – collective protection : cyclairs

- Cyclair depends on contamination Iodine - aerosols – iodine and aerosols
- Under the responsibility of the SRP officer
 - Filters choice
 - Control of the efficiency when operating
- Under the responsibility of the general services
 - Assembly and desassembly of cyclairs
 - Changing the filters

It is forbbiden to put in operation an unscealed cyclair : proof of the presence and efficiency of the filter







Contamination – collective protection : cyclairs





Mobile equipment

Filtering box


Ventilator





Protection means in controlled area

Contamination – collective protection : cyclairs







Contamination – individual protection

Internal contamination by ingestion







LE TOP DES INTOLÉRABLES

sur le site de Tihange

BOIRE OU MANGER EN ZONE CONTRÔLÉE !



Electrabel



Contamination – individual protection

Internal contamination by cutaneous transfert :

Do not enter in controlled area with open wounds



Protective clothes : correct dress in controlled area or specific equipment









Contamination – individual protection

Specific gloves



Where to find ? In stores of each unit !





Contamination – indivual protection : mask

internal contamination by <u>inhalation</u> → wear a mask or `helm'





Be careful : those equipment should be packed and have protective cap





Contamination – individual protection : mask

cartridge P3 / dust

Filter for particles of toxic agents (carcinogen, radioactive, bacteria, virus, enzimes)

- Unpack from its plactic bag
 - Screw correctly on the mask

Verify the airtightness







Contamination – individual protection : mask

Filter Reaktor/St

Filter for particles (P3) + iodine (orange band)

Take out the cap

Screw correctly on the mask

Verify the airtightness







Contamination – individual protection : 'helm'

Characteristics of `helm' /Gridel + respiratory protection + good neck protection + belt with air tap

Advantages : + mechanical resistance + Visibility + Comfort



Disadvantage : - adduction by pipe





Contamination – individual protection : mask + gas cylinder

Respiratory device PSS 100 Training is needed











Contamination – individual protection : body



Specific overalls





Contamination – individual protection : body - Flexothane

Characteristics :

- + Flexothane jumpsuit
- + Elastic on wrist and heigth
- + Buttons on neck, wrists and ankles
- + waterproof

Usage :

+ protection against liquid spatters



Advantages : + Durable + light + Hood Disadvantages :

- not useful for aerosols
- not hermetic for neck and ankles





Contamination – individual protection : body - Mururoa

Characteristics :

- + full protection, ventilated
- + airtightness
- + air adduction (aircylinder or pipe)

Usage :

+ contaminated atmosphere

Advantages :

- + full protection
- + Double back fastening
- + fireproof
- + protection factor
- + mechanical resistance
- + light




Disadvantages :

- bulky
- air adduction





Protection means in controlled area






Irradiation – protection means

Time

Dose (mSv) = Dose rate (mSv/h) * time (h)








Irradiation – protection means

Distance

Dose $\approx 1/d^2$



Distance (m)	Dose rate (µSv/h)	Dose (µSv) absorbed in 15 min
10	1	0,25
1	100	25
0,5	400	100
0,1	10.000	2.500
0,01	1.000.000	250.000

Keeping away from sources Remote-control equipment






Irradiation – protection means

Shielding


The nature of shielding depend on

- Type of radiation
- Energy of radiation
- location of shielding

For each material :



Half Value Thickness (HVT) and Tenth Value Thickness (TVT)





Irradiation – protection means Exercise:

We work on a valve containing a contamination of 1 GBq (27 mCi) of Co-60

Dose rate at 1 m (source without shielding) = $3,6.10^{-1}$ mSv/h

- I work at 10 cm : Dose rate = ??
- I work with 5 cm of Pb (lead) shielding : Dose rate = ??

- I work during 10 min : dose = ??

- I use a tool of 20 cm length : dose = ?? Culture de Sûreté v03-20140101









Protection means in controlled area









Don't forget !

- Compliance with SRP instructions
- protection means
 - Contamination risks :

Suitable collective (e.g. Cyclairs) and individual means of protection

- Irradiation risks :
 - Time
 - Distance
 - Shielding





Principles and means of radiation protection

- Risks in controlled area
- Justification Dose limits Alara
- Signaling in controlled area
- Means of protection in controlled area
- Dosimeter



Dosimeters



Measurement of irradiation dose







Measurement of irradiation dose : Passive dosimeter

Where to ask for ? Acces building

Who ? all persons professionally exposedHow to wear it ? On the chestWhen ? Always in controlled area



Electrabel

OSL

BeOx

GDF SVez


Where to stock ? In the racks at the entrance of the site

Never leave the power plant with your dosimeter





Measurement of irradiation dose : Passive dosimeter - OSL





Culture de Sûreté v03-20140101

Electrabel

GDF SVez



Measurement of irradiation dose : Passive dosimeter - neutron

Neutron dosimeter

Electrabel



Who ? Every worker who enter in the nuclear reactor building in operation, for used fuel transfer or in some rooms with neutrons sources.

How to wear it ? On the chest Where to find it ? At the SRP office in the controlled area Where to bring it back ?

At the SRP office in the controlled

area



Dosimeters



Measurement of irradiation dose : Active dosimeter Electronic dosimeter



Who ? all persons professionally exposed How to wear it ? On the chest Where ? Always in controlled area

Where to find it ? In the racks at the entrance of the controlled areaWhere to stock it ? In the racks at the entrance of the controlled area







Measurement of irradiation dose : Active dosimeter

- If the alarms sounds
- **Stop immediately** your activity (Secure your activity)
- Keeping away (going to "green area")
- Call a SRP officer
- Waiting for the instructions and follow them.







Dosimeters



Measurement of irradiation dose : Active dosimeter

Two types of alarm:

If 'dose' alarm :

- 3 short bips/s



- The message 'Dose Alarm' flashes

If **`Dose rate'** alarm :

- 3 long bips/s



- The 2 messages 'Rate attention' and 'Rate Alarm' are successively displayed

Remark : In the case of concurrent dose and dose rate alarms, the dosimeter successively emits 3 short bips and 3 long bips





Don't forget !

- Where to aks for a dosimeter ?
 - At the acces building
- Who?
 - All professionally exposed persons
- Where is worn ?
 - On the chest
- When ?
 - Always in controlled area
- Where to stock ?
 - In the racks at the entrance of site (passive dosimeter)
- Never leave the nuclear power plant with your dosimeter !





Don't forget !

- If the alarm of your electronic dosimeter sounds :
 - Immediation stop of your activity (with securisation)
 - Move to a "green area"
 - Call a SRP officer
 - Wait for its instructions and follow them !!











Awareness on safety culture, security, radiation protection and environment.

Protection means

SUMMARY – TO RETAIN





Questions

1. If I receive doses, am I radioactive ?





1. If I received doses, am I radioactive ?



- Irradiation by alpha, beta and gamma ray don't make matter radioactive.
- Contamination radiates
- Irradiation can not contaminate





2. The three basic principles of radiation protection are :

- Irradiation, contamination, dose ?
- Justification, doses limitation, ALARA ?
- Time, distance, shielding ?





2. The three basic principles of radiation protection are :

- Irradiation, contamination, dose ?
- Justification, doses limitation, ALARA
- Time, distance, shielding ?





3. ALARA principle =

- Dose = 0 ?
- Dose correctly justified ?
- As low as reasonably achievable





3. ALARA principle =

- Dose = 0 ?
- Dose correctly justified ?
- As low as reasonably achievable





Questions

4. What is the dose rate in a « orange » local :

- < 20 µSv/h ?
- > 20 µSv/h ?
- > 200 µSv/h ?
- > 1 000 µSv/h ?





Questions

4. What is the dose rate in a « orange » local :

Ionizing radiations < 20 μSv/h

Ionizing radiations > 20 μSv/h

High intensity of ionizing radiations > 200 µSv/h

Very high intensity of ionizing radiations > 1000 μ Sv/h





5. The three means of protection against irradiation are :


- Distance, time, shielding
- Distance, dosimeter, shielding
- Distance, dosimeter, time






5. The three means of protection against irradiation are :

- Distance, time, shielding
- Distance, dosimeter, shielding
- Distance, dosimeter, time







6. The individual means of protection are :

- Chosen by the worker ?
- Recommended by the CdT ?
- Randomly selected in the racks ?
- Made mandatory by the SRP instructions ?





6. The individual means of protection are :

- Chosen by the worker ?
- Recommended by the CdT ?
- Randomly selected in the racks ?
- Made mandatory by the SRP instructions











Electrabel

GDF SVez

6. The individual means of protection are :

N° de DDC :			Chantier :						
Electrabel	EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :	
GDF SVez	BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :	
	DATE :Du	au		AGENT SRP	Nom :	Trig :		SRP :	
Mesu	es d'irradiation		Travail à risque élev	vé: O / N si oui, motif :					
			Risques identifiés :						
Date Au poste de travail (µSv/h)							_		
	(µSWII)] 🔬		
			Consignes pour inte	ervention :					
							•••••		
]		••••••	•••••	•••••	• • • • • • • • • • • •	•••••
							•••••		
Mesures de contaminati	on et de sécurité a	vant ouverture		••••••			•••••		•••••
Date contamination surfacique (Bq/cm ²)	contamination atmosphérique (Bq/m ³)	sécurité (% LIE H ₂ ,% O2, T° WBGT)			•••••••		•••••	· · · · · · · · · · · · · · · · · · ·	·····
	(Bqritty)		1		••••••	•••••	•••••		•••••
							•••••		
			Point d'arrêt :			L	evé par:	VISA:	Date:
Mesures de contaminati	on et de sécurité a	près ouverture							
Date contamination surfacique (Bq/cm²)	contamination atmosphérique (Bg/m ³)	sécurité (% LIE H ₂ ,% O2, T° WBGT)							
			Consignes pour accès :						
]		
			••••••						•••••
re de Sûreté v	03-201401	01							
e au surete v	45 ZUI TUI								

494



7. In case of alarm on my electronic dosimeter :

- I stop my activity and secure my work place
- I leave my work place and I go to the green area
- I call a SRP officer
- I wait for a SRP officer and follow his instructions
- All four responses are corrects





7. In case of alarm on my electronic dosimeter :

- I stop my activity and secure my work place
- I leave my work place and I go to the green area
- I call a SRP officer
- I wait for a SRP officer and follow his instructions
- All four responses are corrects





Awareness on safety culture, security, radiation protection and environment.

Entry and exit in controlled area



Table of contents (3)



Entry and exit in controlled area

- Enter in a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination





Material entrance



- Warn a SRP officer
- No unnecessary equipment
- Remove the packaging







Material entrance : To remember ! ZONE CONTROLEE



Useless packaging







Transparent plastic





Culture de Sûreté v03-20140101

Less risks !

Less wastes !





Material entrance : To remember !

- FME: transparent plastic is forbidden
- <u>Exceptions</u>: Packaging of filters P3 BUT there must be the FME sticker !



Persons entrance



Persons entrance

Don't try to introduce equipment by the changing rooms.

Only keys, dosimeters, badge and document are allowed.



Table of contents (3)



Entry and exit in controlled area

- Enter in a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination





Why we should follow the entry and exit instructions:

• To limit the **contamination risks**.

Who?

• Everybody except the rescue teams exclusively during emergency situations. (ex : firemans, EPI, ...)

When?


• During each entry and exit



Persons entrance



Controlled area organization







Persons entrance

Cold changing room

Ask for a loker (in access building) before your entry to the site.

Once your locker is no more used, bring back the key to the access building.





Hot changing room access

Entrance in controlled area is done only on underwear.

Avoid wearing unncessary accessories (watch, jewel, etc...)

Tenue pour l'accès au vestiaire chaud :



L'accès au vestiaire chaud se fait exclusivement en <u>sous – vêtements.</u>







Controlled area entrance for persons

Hot changing room access

To bring :

- Security glasses
- Personal passive dosimeter
- Acces badge



- Electronic dosimeter (In the racks at the entrance of controlled area)





Hot changing room access

- Insert your electronic dosimeter
- Present your access badge
- Enter your "job"code or your "work site" code

If problems, call dosimetry service




	Toute utilisation d'un autre numéro que ceux m devra faire l'objet d'une autorisation préalable d	
_ <u></u>	Autorisations "Métier"	Limite journalière (µSv)
3001	Operations - Exploitation	20
3002	Operations - Chimie	20
3003	Operations - Déchets	20
3004	Operations - Support	20
3005	Operations - GAP Révisions	20
3006	Operations - Formation	20
3007	Maintenance - Gestion des révisions - 0 GRP	20
3008	Maintenance - Housekeeping - 0HK	20
3009	Maintenance Mécanique - 0MG	20
3010	Maintenance Mécanique - 0MDP	20
3011	Maintenance Mécanique - 0MT	20
3012	Maintenance Mécanique - 0 MSE, 0 MSP, 0 MSM	20
3013	Maintenance Robinetterie - 0 VM	20
3014	Maintenance Robinetterie - 0 VE, 0 VI	20
3015	Maintenance Robinetterie - 0 VAS, 0 VAI	20
3016	Maintenance Robinetterie - 0 VAP, 0 VAR	20
3017	Maintenance E&I- 0EE, 0ED	20
3018	Maintenance E&I- 0EL	20
3019	Maintenance E&I- 0IT, 0IR	20
30 20	Maintenance E&I- 0IC, 0IP	20
3021	Maintenance - Mécanique Tranche	20
3022	Maintenance - Electricité Tranche	20
3023	Maintenance - Instrumentation Tranche	20
3024	Engineering	20
3025	CARE SRP	20
3026	CARE Environnement	20
3027	CARE Sûreté nucléaire	20
3028	FUEL	20
3029	PPM	20
30 30	Cadres et Direction	10
3031	TC - Communication - Informatique - 0 QP	10
30 32	Zones surveillées (hors zone)	5
3051	Visites	500
3052	Bel V	303
3053	Laverie	10
3054	Nettoyage	20
3055	Atelier de décontamination	20
30.50	Divers	5

Persons entrance



Controlled area organization







Dressing in hot changing room:

- Helmet
- Cap *
- White cotton overalls
- Tee-shirt *
- Shoes
- Socks
- Cotton gloves
- Safety glasses

(* facultative)





CONTROLATOM

Persons entrance



Video illustration Hot changing room access + Dressing





Table of contents (3)



Entry and exit in controlled area


- Enter in a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination





de l'estellence

Electrated 0








• Before starting an activity we must, for our own security and the security of other colleagues, question about work conditions arround us.

• For all work with <u>DDC</u> (not generic), we should realize and formalize the **local site opening**.

• The **security cards** were developed with similar aim, for all activity <u>without DDC or with generic DDC</u>.





516

CONTROLATOM



Works with DDC → local site opening

When ? Before starting

Where ? Always on intervention area \rightarrow <u>local</u>

Aim ? Confirm that the conditions defined in the work permit are respected.

Intervention on correct equipment (labelling), accordance of installation conditions, presence and compilance of protection means. Checking the work site environment (interaction with other work sites). confirm the knowledge of instruction for all intervening.



GDI/GPI/004



Works with DDC -> local site opening

Interrogative attitude !



What is the problem?









To check one security before intervention

Check the consignation effects – Included in local site opening documents

Examples :

- pressure gauge
- > Open purge
- > Temperature of the equipment
- » Electrical cells are locked
- > To work loose slowly a flange ,
 - to check the lake of pressure





Electrabel


Fill-in correctly the following form local site opening

						,					Date :					
N° DDC	:									le travau						
EEX:							EEX : N	om ch	nargé d	le travau	x					
JB reg	çu: Ora	al	ок	Form	alisé	ок	NOK		Repè	ere fonct	tionnel :					
	<u> </u>	DDC			OF	пон	K NA					nt de chant résiduels	tier	ОК	N OK	NA
	us sur le l	bon rep	père					11		ns de se	cours acc	essibles et dis	ponibles			
fonction	nel ? nes d'in:	stallat	ion (le la Di				- +	-		xtincteur	nt connues e	t libros ?			
Les con adaptée	signes d'i	installa	tion :]		Les c			l sont accepta				
Le circuit vannes d	t est dépre de drain et ètre à 0,,	essurisé d'évent	et vid		s,					hantiers v émentair		apportent pas	de risques			
La ligne (et/ou l'équ	uipemer	nt est	froid ?					Les é	chafauda	iges sont i	réceptionnés	?			
consigné										roduits d age est p		sont étiqueté	is ?			
	de tension nes d'ex			a la DD	c			-		ngins et a de contr		s de levage s	ont en			
Les con	onsignes d'exécution de la DDC ordre de contrôle ? Les risques de chute et trébuchement sont Japtées ?															
Les moyens de prévention définis Les moyens de prévention définis Les pièces chaudes sont protégées ?																
Les moy	es moyens FME nécessaires sont en Les équipements saillants sont protégés ?															
APPEL		de PIU									er en séc	urité puis év	/acuer			
Date		lom		p p	Prén			Visa	-	Date	No	m	Prénom		,	Visa
Travau	x à risque	es élev	és su	ivant pr	rocédu	re PRE	v/inst	R/301	(Cons	igne 010	1 cochée	dans la DDC)		c		NON
Pour le	s travaux	c à risq	ues é	levés (chargé	de tra	vail EBI	. avec	agent	SRP)						
					O	(NOI	KNA	╷ ,						OK	NOK	NA
Le chan	ntier est b	alisé									e consigne lidé par C	es est placé à ARE SRP	l'entrée du			
	sures prés es (T°, O ₂		sont			1										
Si vous <u>Mesure</u>	avez rép es complé	oondu I										esponsable E	BL			
Vicito						FI	abelno	ur les	travau	IV à risou						
				<u>té de tra</u>	avaux	Electra					CS CIEVES					
		ne du (Comme			avaux	Electra		sa		Date	Trig	Commentair	es		Vis	a
	<u> </u>				avaux	Electra		sa					es		Vis	sa
	<u> </u>				avaux_	Electra		sa					es		Vis	a
	<u> </u>				avaux	Electra		sa					es		Vis	sa

520

OUVERTURE DE CHANTIER EN LOCAL

Electrape



521



Travaux à risques	élevés	suivan	t procédure PREV/INSTR/301 (Consigne 010)1 cochée	dans l	a DDC)	OUI/	NON
Exercised Servers de l'andre de la de l		e chanti es mesu orrectes <i>i vous a</i> r	res préalables sont	DK NA Image: I	Le panneau chantier et	validé pa		OK N	NOK NA
Description Transmission Transmission Transmission Description Transmission Transmission Transmission Provide Transmission Transmission Operation Provide Transmission Transmission Operation Provide Transmission Transmission Operation Operation Provide Transmission Transmission Operation Operation Operation Provide Transmission Transmission Transmission Operation Operat	Vicita	quotidia	enne du Chargé de travaux Electrab	al pour les trav	auv à ricqu	es álevá			
7	Date	Trig	Commentaires	Visa	Date	Trig	Commentaires		Visa
				_					





Case of high risk works (reminder) :

- The engineer in charge (CdT) should be a Electrabel CNT person,
- The CdT and the SRP officer do **local site opening** with all participants (+ signatures !),
- The CdT marks up the work site,
- The SRP officer put the **messages board**,
- The CdT <u>do a daily visit</u> of the work site (to ensure that the work site is conform, to check if the rules are respected, ...) and fill-in the following form.






Electrabel

ectrabel		PERMIS DE T BECT / Tihange	RAVAIL 2 / 2EM	DDC 1550469
POSTE TECHNIQ		567 I-RET.S/BONBONNE	S H2 CIRC.8	
LOCALISATION : Description: Phase Révision:		LOCAL: uite au raccord situé e		TD ann.1: X
DEBUT DU TRAV	AIL:05.07.2011	00:00:00 FIN DU	TRAVAIL:05.07.	2011 00:00:00
Date: 05/07/		avaux Responsabl	le Installations Ct	arge des travaux
Changement du	Chargé des tra	VAUX		
Date:	Date:	Date:	Dat	e:
Nom:	Nom:	Nom:	Non	
Signature:	Signature:	Signature:	Sigr	ature:
PARTENAIRES DDC	Nom		Date	Signature
Int.Resp.de travail		is Lantin		
PERMIS SUPERVSION	Permis par L REMACLE	Date 01.07.2011	TD ann.1 LDC 596907	
AGREE	C PINTE	04.07.2011		
REVIEW SAFETY	R RADOUX B ROBA	04.07.2011 04.07.2011		
SECURE	C PINTE	05.07.2011		
REQUALIF				
INSTALLATION 25-CIRC CI20	Circuit DOIT être vide	e & Hors pression		TD_ann.1
		, co nono presion		Х
01-TVX 0101	Travaux à risques élev	ráe		TD ann.l
09-3INC 0931	Risques liés à une zon	e AIEX		
11FME 1102	Niveau FME standard			
14ROC 1401				
14-1RCH 1411	Compléter le check lis	t replis chantier		
15MPI 1501	Moyens de prot.individ	luels requis		
99MYSELF 100	Voir short text ou long voir agent RP	g text		X
ORDRES				
	n de la fuite au raccord PCT2-AGH-C567 CLAPET ANTI-		CIRC.8	Liste d'obj. ann.)

Atrabel OUVERTURE DE CHANTIER EN LOCAL DF SUCZ Date : 06.09 11 N° DDC : 1550464 EBL : Nom chargé de travaux EEX EEX : Nom chargé de travaux OK OK NOK AGH Repère fonctionnel : C 567 PJB reçu: Oral Formalisé Environnement de chantier DK NOK NA DDC OK NOK NA **Risques résiduels** Étes-vous sur le bon repère Moyens de secours accessibles et disponibles fonctionnel? 1 (tél, douche, extincteur, ...) ? Consignes d'installation de la DDC Les issues de secours sont connues et libres ? K Les consignes d'installation sont X Les conditions de travail sont acceptables (T', adaptées K éclairage)? Effets de la consignation Le circuit est dépressurisé et vide (les Les chantiers voisins n'apportent pas de risques vannes de drain et d'évent sont ouvertes, × X supplémentaires ? monomètre à 0, ...) ? La ligne et/ou l'équipement est froid ? N Les échafaudages sont réceptionnés ? K Les produits dangereux sont étiquetés ? Cellule électrique 6 kV, 380 V, 8 X Stockage est prévu ? consignée ? Absence de tension auxiliaire R. Les engins et accessoires de levage sont en Consignes d'exécution de la DDC 凶 ordre de contrôle ? Les consignes d'exécution sont Les risques de chute et trébuchement sont × adaptées ? X protégés ? Les moyens de prévention définis SF 1 Les pièces chaudes sont protégées ? sont mis en place ? Les moyens FME nécessaires sont en K Les équipements saillants sont protégés ? place ou disponibles ? X RAPPEL : en cas de PIU (mise à l'abri ou évacuation) : mettre le chantier en sécurité puis évacuer Signatures des intervenants pour prise de connaissance des consignes Date Nom Prénom Visa Date Nom Prénom Visa 7 11 10 P Travaux à risques élevés suivant procédure PREV/INSTR/301 (Consigne 0101 cochée dans la DDC) OUI / NON Pour les travaux à risques élevés (chargé de travail EBL avec agent SRP) OK NOK NA OK NOK NA Le panneau de consignes est placé à l'entrée du Le chantier est balisé ×. *A* chantier et validé par CARE SRP Les mesures préalables sont correctes (T*, O2, ...) Si vous avez répondu NOK à une des questions, contactez votre chef d'équipe ou le responsable EBL Mesures complémentaires prises : Visite guotidienne du Chargé de travaux Electrabel pour les travaux à risques élevés Date Trig Commentaires Visa Date Trig Commentaires Visa

Culture de Sûreté v03-20140101

1/2 525



du Charge de travaux Electrabel pour les

Culture de Súreté v

Trig

40





Works without DDC or with generic DDC → Security cards

Security cards

GDF SVez

- Help for continuous alertness / vigilance
- > Quick reference
- Key questions + attitude we should adapt
- > 7 cards « job» + 1 card « field visite »
 - Job SRP
 - Job Test
 - Job Fuel
 - Job Chemistry

- Job Operation
- Job Maintenance
- Job Waste
- Field visite



Culture de Sûreté v03-20140101

PREV/INSTR/299





Works without DDC or with generic DDC → Security cards

Everyone should have its own unique card.


It is not mandatory to have it with you **BUT** you should know its content.





de l'estcellence

Electroles.



529

CONTROLATOM




Respect the instructions of the messages board

		N° de DDC :			Chantier :						
Electr	abel	EQUIPEMENT :			Chargé de travaux EBL	Nom :	Trig :		Tél./Bip :		
		BATIMENT :		LOCAL :	Chargé de travaux EEX	Nom :	Trig :		Tél./Bip :		
GOF		DATE :Du	au		AGENT SRP	Nom :	Trig :		SRP :		
				Travail à risque élev							
Mesures d'irradiation				Travail à risque élevé : O / N si oui, motif :							
Date		Au poste de travail (µSv/h)									
				Consignes pour inte	ervention :						
					•••••••	••••••••••••••••••••••••	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · ·			
Magurag da			ant curature			· · · · · · · · · · · · · · · · · · ·			•••••		
wesures de	contamination	n et de sécurité av	ant ouverture								
Date	contamination surfacique (Bq/cm²)	contamination atmosphérique (Bq/m³)	sécurité (% LIE H ₂ ,% O2, T° WBGT)	· · · · · · · · · · · · · · · · · · ·	••••••	•••••••	••••••	· · · · · · · · · · · · · · · · · · ·			
Date c	surfacique	atmosphérique	sécurité (% LIE H ₂ % O2, T° WBGT)					· · · · · · · · · · · · · · · · · · ·	·····	·····	
Date C	surfacique	atmosphérique	sécuritê (% LIE H _a ,% O2, T² WBGT)	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·			Levé par:	VISA:	Date:	
Date C	surfacique	atmosphérique	sécurité (% LIE H ₂ % O2, T° WBGT)	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·			Levé par:	VISA:	Date:	
Date	surfacique (Bq/cm²)	atmosphérique	(% LIE H ₂ % O2, T° WBGT)	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·		Levé par:	VISA:	Date:	
Mesures de	surfacique (Bq/cm²)	atmosphérique (Bq/m³)	(% LIE H ₂ ,% O2, T° WBGT)	Point d'arrêt :	· · · · · · · · · · · · · · · · · · ·			Levé par:	VISA:	Date:	
Date Date Control Date Date Date Date Date Date Date Date	surfacique (Bq/cm²)	atmosphérique (Bq/m³)	(% LIE H ₂ % O2, T° WBGT)	·····				Levé par:	VISA:	Date:	
Date Date Control Date Date Date Date Date Date Date Date	surfacique (Bq/cm²)	atmosphérique (Bq/m³)	(% LIE H ₂ % O2, T° WBGT)	·····	<u></u>			Levé par:	VISA:	Date:	
Date Date Control Date Date Date Date Date Date Date Date	surfacique (Bq/cm²)	atmosphérique (Bq/m³)	(% LIE H ₂ % O2, T° WBGT)	·····	:ès :			Levé par:	VISA:	Date:	
Date	suffacique (Bq/cm²)	atmosphérique (Bq/m³)	(% LIE H ₂ ,% O2, T° WBGT) près ouverture sécurité (% LIE H ₂ ,% O2, T° WBGT)	·····	: <u>ès :</u>			Levé par:	VISA:	Date:	



Intervention

Do not forget to place a correct mark-up.








de l'estellence

Electrated 0







When ? During the intervention for the breaks or at the end of your day.

Where ? In local

How ?

- Store equipments,
- Sort waste,
- Don't leave your tools under voltage,
- Correct mark-up,
- Put all control panels on storage position





Put the installation and its environment in accordance with the defined operating standards.









When ? After the intervention

Where ? In local

How?

- According to the check list on the back of the form "local site opening".
- Under the responsibility of CdT or CdT EBL (for high risk works),
- Should be validated by SRP if asked in the DDC or in the SRP instructions.




Electrabel

Demobilization

	<u>Be</u>	<u>Repli en Ordre</u>		Commentaires
	ок	NO K*	NA	
Le chantier a-t-il été contrôlé par un agent SRP <u>(si demandé par les consignes RP à l'entrée du chantier</u>) ? - Local et <u>áquipements</u> ? - <u>Qutils</u> ?				Si non, contacter l'agent SRP.
A-t-on évacué le matériel et l'outillage ?				
Le matériel et l'outillage sont-ils décontaminés et remis en état ?				
Le chantier est-il décontaminé ?				Si non, prévenir les SG de la fin de chantier
Le chantier est-il nettoyé (Nettoyage <u>final</u> local et équipements) ?				Si non, prévenir les 56 de la fin de chantier
Repérage (étiquettes, labelling,) remis en conformité ?				
Réfection des peintures dégradées durant l'intervention réalisée ou planifiée ? (Local et <u>équipements</u>)				
Signalétique relative au chantier (balisage, affiches, "carte de défaut") retiré ?				
Les coffrets électriques sont ils verrouillés ?				
Déchets évacués vers les lieux de stockage prévus à cet effet ?				Si non, prévenir les SG de la fin de chantier
Echafaudages démontés ? **				Si non, prévenir le coordinateur d'échafaudage
Pénétrations coupe-feu correctement refermées ?				
Engins de manutention en position de garage ?				
Dalles, cailebotis, garde-corps correctement remis en place ?				
Calorifuge correctement remis en place ?				

* Dans les cases ou vous répondez NON : rédiger un avis et l'inscrire en commentaire (sauf commentaire existant).
** pour équipement de sûreté l'échafaudage doit être démonté avant fin requalification

	Trigramme	Visa
Validation Chef de Travaux :		
En zone contrôlée, <u>tout</u> repli de chantie Suit Etre val de par la SRP (<u>si</u> 010) demandé par les consignes RP à l'entrée du chantier) :	1	





COT



Demobilization

The demobilization form + DDC, return to the person who's issued the DDC.





Demobilization





Table of contents (3)



Entry and exit in controlled area

- Enter in a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination





Equipment = ?

- PMP (SPE) : small personal equipments (see personal exit)
- DHF (HWD) : Homogeneous waste in drums (loose)
- PMD (SEW) : small equipments and various waste
- GMD (BEW) : big equipments and various waste



RP/00/011




Control of the contamination

- In SRP office near the exit for equipment
- Control of surface and mass contaminations










Decontamination control







Sortie de zone pour le matériel

Work with risk of contamination : how to transport material ?

Avoid contamination transfert !





Added constraint : if alpha risk : double packaging !

Keep the bag with the order form !



Culture de Sûreté v03-20140101

RP/00/011

Electrabe	Electrabel@ SV@ZDemande de contrôle et de suivi de la contaminationPour le responsableCNT Xde la contaminationN° xxxx
GDF SVC:	Demandeur : Bip : Date : /
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	NOM DE L'AGENT DECONTAMINATION: MOYEN(S) UTILISE(S): COMPTE RENDU: Réexamen éventuel de la demande de décontamination : OUI / NA Décision finale prise: TERMINE LE: / / VISA du demandeur pour accord: VISA du responsable:
Culture de Sûrete	$\begin{array}{c c c c c c c c c c c c c c c c c c c $





- Decontamination room
- Bring the objects which should be decontaminated with the request document.
- Be careful to contamination transfer !





Table of contents (3)



Entry and exit in controlled area


- Enter in a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination



Persons entrance



Controlled area organization







C1 Control (Nardeux)

- Objective : control the contamination of your dress
- Means : beta detectors
- How ? Enter with your full dress (With your gloves)





C1 Control

- Objective : control the contamination of your dress
- Means : beta detectors
- How ? also for your small equipment/object (CBO)







C1 control









If clean → Hot changing room → undressing

- Be careful to undressing
- Separate your dress
- Close your locker and, if your work is finished : mention it and release your locker










Controlled area organization







C2 control

- Between the hot changing room and the cold changing room : <u>IPM9</u>
- Means : beta and gamma detectors
- How ? Only with underwear, after you badged









C2 control

• Control of small objects









C2 monitoring

- Control front and back sides
- If clean : clearly indicated



PROPRE - Quitter S.V.P. Reprenez vos objets



If clean -> Cold changing room

- Badge (Electronic dosimeter + passive dosimeter)
- Put back your electronic dosimeter in the rack !!
- Go to the "cold changing room"
- Dressing with your own clothes
- At the end of your work : bring back your keys (Access building)





556



Video illustration Exit from controlled area





Table of contents (3)



Entry and exit in controlled area

- Enter to a controlled area
- Personal entrance
- Intervention in controlled area
- Material exit
- Personal exit
- Decontamination





In case of contamination?

All contaminated person Should call a SRP officer





Culture de Sûreté v03-20140101

RP/INSTR/301



In case of contamination ?

The following steps are undertaken :

1) Person decontamination :

By itself (after SRP agreement), With the help of SRP, With the help of CBMT (declared to FANC !). CBMT = medical center in Tihange power plant 2) In parallel with first step, fill the form for declaration of

contaminated person.

Contamination in controlled area is not a normal event !



In the case of contamination?

Electrabel

GDF SVez

FORMULAIRE – FICHE DE DECLARATION DE PERSONNE CONTAMINEE						
Fiche de déclaration de personne contaminée						
Date: / / SRP EBL	Trig:	Vis	a :			
Heure : SRP EEX	Firme :	No	m :			
1. Identification de l'agen	t contaminé					
<u>Nom</u> <u>So</u>	<u>ciété 🗌 EBL</u>	Service				
Prénom		Firme				
2. Localisation - quantifica	ation - déconte	aminatio	on			
Localisation Tête Corps Mains Bras Jambes Jambes Pieds Petit matériel Sandales Technique de décontamination utilisée :	décontan Béta Gamma	é mesur ée vant ination(Bq)	A ctivité résiduelle avant intervention C B/IT (Bq) Béta domino			
3. Travail réalisé par l'age	nt					
Permis de travail n° <u>Equipement</u> : <u>Repère fonctio</u> <u>Autre</u> : A préside] 1 🔲	2 [] 3 			
Tâche effectuée : A prédicer Culture de Sûreté v03-20140101						

Clas. Code (Réf.) : ZNO 10010018496.000.01	- Date : 26/03/10 - MWC Publisher : PCT CSR	L - Doc.mère :RP/INSTR/301 : ZST10010017810/000/01

Fiche de déclaration de pe	Page:2/2						
4. Actions SRP : recherche de l'origine de la contamination							
<u>Lieu de détection</u> : □ C 0 □ C 1	C2 Autre : A présiser						
Nombre de passages au portique:	 <u>N° portique : .</u>						
Mesures de contamination sur le lieu de travail Préder résultat							
Action(s) corrective(s) prise(s) A prédeer							
<u>Cause de la contamination</u> :							
Non respect du port des MPI	<u>Contact avec du matériel contaminé</u> A présisor						
Problème habillage / déshabillage							
Non respect des consignes SRP							
Confinement chantier	Pratique de travailinadéquate						
Tenue de zone Aprésisar	A prédiser						
Défaillance technique A présiser	Autre(s) A prédisor						
5. Appel au CBMT - Demand	e passage anthropo						
	Suivi						
Demande de passage à l'antropo au CB	<u>MT (</u> au plus tard le jour ouvrable qui suit)						
6. Encodage dans base de do	nnées						
Date: / / Trig:							



Video illustration Contamination management







Persistent contamination → Possibility of a medical examination with radioisotopes ?

	AUTORISATION D'ACCES AU SITE DE LA CENTRALE
	Tihange, le
	Monsieur est autorisé à accéder sur le site de la centrale nucléaire de Tihange, hors zone, bien qu'il déclenche les balises d'accès.
	L'accès en zone contrôlée est suspendu duauau
	A revoir au service médical le
	Centrale Nucléaire de Tihange Avenue de l'industrie 1
	4500 TIHANGE
	☎ 085/24.30.02 Fax 085/24.30.09
Culture de	@. cbmt.tibange@electrabel.com





Are we clean enough ?

Exit of IPM9 detector in controlled area

In operation (2013)	Τ1	T 2	Т 3
Number of passages	34.193	62.843	38.486
% alarm	0,9	1,2	0,7
Overhaul (2013)	Τ1	Т 3]
% alarm	1,6	1,6	1

Site average in 2013 = 1,2%





Don't forget !

RIGOR

- Entrance in controlled area
 - Respect of ruls : rigour
 - Not superfluous materials
- Before
 - With DDC
 - Without D
- After wo
 - The imp
- Exit or controlle
 - Material contr
 - Personal detector
- In the contamination case
 - Always call SRP











Awareness on safety culture, security, radiation protection and environment.

Entry and exit in controlled area

SUMMARY – TO RETAIN





Questions

1. Can I bring equipment with me in controlled area ?





1. Can I bring equipment with me in controlled area ?

- Yes :
 - Small objects (badge, dosimeters and documents) through entrance for the personal
 - Equipment through the equipment entrance, I should call a SRP.
 - Don't bring with yourself the unuseful materials.





2. To go from the cold changing room to the hot changing room, I should wear :

- My underwears (shorts)
- A long short and a sweat shirt
- My underwears and a pullover if I am cold
- Nothing





2. To go from the cold changing room to the hot changing room, I should wear :

- My underwears
- A long short and a sweat shirt
- My underwears and a pullover if I am cold
- Nothing





Questions

3. The dress in controlled area consists in :





Questions

3. The dress in controlled area consists in :



- Helmet
- Cap *
- White cotton overalls
- Tee-shirt *
- Shoes
- Socks
- Cotton gloves
- Safety glasses









4. If I respect the local site opening and the messages board, I do not run any risks ?





4. If I respect the local site opening and the messages board, I do not run any risks ?

- FALSE !!!
 - I should always have an interrogative attitude and I look after my own security, the security of other colleagues, and the environment.







Basis training

Agenda

Day 1 - 2 - 3 : ISNES

8h	10h 10h15'	12h15' 12h45'	14h30' 14h45'	16h30'

Day 4 : NPT

8h	9h45'	10h	1:	2h 1	2h30'	15h	15h15'	16h30)'
Training wo Preparatio	ork on		ining work y demobilization		Training work Demobilization & Debriefing		Test	End	

Meeting: 7h30 Access building





ADR Accord européen de transport par route de matières dangereuses

- AED circuit dEau Desionisée Alternateur
- AFCN Agence fédérale de controle nucléaire
- AIEA Agence Internationale de l'énergie atomique
- ALARA As Low As Reasonably Achievable
- AT Arrêt de tranche
- **ATEX** Atmosphère explosible
- **BAN** Bâtiment des auxiliaires nucléaires
- **Bel-V** Filiale de l'AFCN chargée des inspections
- BR Bâtiment réacteur
- **CBMT** Service médical au travail
- **CCV** Circuit de controle chimique et volumétrique
- CdT Chargé de travaux





CMR Cancérigène, mutagène et toxique pour la reproduction (tératogène)

- CMS Chemical Managment System
- **CNT** Centrale nucléaire de Tihange
- **CRP** Circuit primaire
- **CVA** Circuit Vapeur Auxiliaire
- **DDC Demande de déconnexion**
- DDI Dossier d'Intervention
- EBL Electrabel
- **EEX** Entreprise extérieure
- **EPI** Equipier de première intervention
- **ESTER Base de donnée de l'estimation dosimétrique**
- FCR Fibres céramiques réfractaires
- FE Fiche d'expérience





Abreviations

- HAT Hors arrêt de tranche
- **HP Human Performance performances humaines**
- HVT Half Value Thickness
- **IPS** Important pour la sûreté
- LDCA Limite dérivée de concentration dans l'air
- MPI Moyen de protection individuel
- ONDRAF Organisme National de gestion des Déchets RAdioactifs et des matières Fissiles enrichies
- OSL Optically Stimulated Luminescence
- PIU Plan Interne d'urgence
- PPE Personne professionnellement exposée
- **PPSSE** Plan de prévention sécurité santé environnement
- **PWR** Pressurized Water Reactor





Abreviations

- **REX** Retour d'expérience
- **RGIE** Règlement général sur les installations électriques
- **RGPT** Règlement général pour la protection du travail
- SDS Safety Data Sheet
- **SECT** Service externe de controle technique
- SME Système de management environnemental
- SPF Service Public Fédéral
- SRP Service radioprotection
- **TEG** Traitement des effluents gazeux
- **TVT** Tenth Value Thickness
- **WBGT** Wet Bulb Globe Temperature
- ZC Zone contrôlée





Ce document a été préparé par Vinçotte Academy et AV Controlatom pour les formations culture sûreté données aux contractants sur le site de GDF Suez Electrabel Tihange.

Toute reproduction est interdite, sauf accord écrit de la part des auteurs.





Electrabel

Vous avez l'énergie